

TECHNICAL BULLETIN

P071NAS1
23 SEP 2015



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 100-00

Non-Compliance Recall: Passenger Airbag Deactivation Indicator (PADi) Lamp Handbook Supplement

AFFECTED VEHICLE RANGE:

Range Rover Sport (LW)

Model Year: 2014

VIN: 339933-368586

Manufacturing Plant: Solihull

MARKETS:

NAS

CONDITION SUMMARY:

Situation: An issue has been identified on a limited number of 2014 model year Range Rover Sport (LW; L494) vehicles where the Passenger Airbag Deactivation Indicator (PADi) Lamp description in the handbook does not match the operation in the vehicle. The handbook just states the OFF state. Vehicles with the handbook in this condition will not comply with the requirements of Canadian Motor Vehicle Safety Standard (CMVSS) 208-Occupant Restraint Systems in Frontal Impact (Canada) and Federal Motor Vehicle Safety Standard (FMVSS) 208-Occupant Crash Protection (USA).

Action: Retailers are required to **HOLD** only affected new vehicles that are within your control and refrain from releasing the vehicles for **new vehicle sale** pending completion of the Service Instruction detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but **must** have it completed prior to vehicle handover to the customer. Affected vehicles already in the hands of customers should be updated at the next available opportunity.

PARTS:



NOTE: * Owner's Handbook supplements are not available for order via Parts. Owner's Handbook supplements will be supplied to customers free of charge as part of the owner notification process. Refer to Service Bulletin SRE15-16 / SRE15-16C for details on how to obtain copies for retailer use.

DESCRIPTION	PART No./SUNDRY CODE	QTY./VALUE	EXPECTED % of VEHICLES REQUIRING PARTS*
* Owner's handbook supplement - English	LSK 18 02 62 141	1	100

* - Owner's Handbook supplements are not available for order via Parts.

Owner's Handbook supplements will be supplied to customers free of charge as part of the owner notification process. Refer to Service Bulletin SRE15-16 / SRE15-16C for details on how to obtain copies for retailer use.

SPECIAL TOOLS:

No special tools required.

WARRANTY:



NOTE: check DDW to ensure that a vehicle is affected by this program prior to undertaking any rework action.

At the time of confirming a booking for vehicle repair, ensure that all outstanding Recalls and Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code 'P071' together with Option Code 'B'. SRO and parts information is included for information only.

Warranty claims must be submitted or payment within 30 calendar days of completion of the repair.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PARTS/SUNDRY CODE	QTY./VALUE*
P071	B	Place owner's handbook supplement in the vehicle	-	-	ZZZ001	*\$1.00

* - an allowance of US\$1.00 has been provided to cover the cost of placing the Owner's Handbook supplement in the vehicle.

Normal Warranty policies and procedures apply.

SERVICE INSTRUCTION:

1 Place the Owner's Handbook supplement [LSK 18 02 62 141 (English)] in the original Owners Handbook in the vehicle.