



Highland

RIDGE RV

NHTSA#: 15V-834

TC#: 2016-004

Job Code: 9904272

Flat Rate: 0.3

LABELS ARE INCLUDED WITH NOTIFICATION LETTER

ACTION REQUIRED:

Place a CAUTION label on the exterior of tailer adjacent to the side vented termination valve

MODELS / UNITS:

2015 Open Range FW	15388RKS	016393, 016552-554 016810-812, 016888-890, 017133, 017150
2015 3X FW	153X388RKS	017132,01734, .017423-425, 017578, 017905-906, 017983, 018327-336,018553-59, 018709, 018835, 018938, 019003, 019097-098, 019177-182, 019293-296, 019492-495, 019618-622, 019708-709, 019955-958
2016 3X FW	163X388RKS	020217-219, 020654-660, 020786-788, 021135-140, 021374-379, 021571, 021697-699, 021966-1968, 022159-162, 022578-580, 022866-868, 022956-963, 023096-099, 023438-442, 023581-586
2015 Highlander TT	15HT21FBD	18388
2016 Highlander TT	16HT21FBD	020035, 021214,021253-261, 021385-393 ,021472-481, 021526-530, 021990-992, 022136, 022247-258, 023540-542

NO parts to order

Shop Supplies

Isopropyl Alcohol
Shop Rag

INSTRUCTIONS



1. Clean the location where the label will be applied with isopropyl alcohol and a shop rag.
2. Remove the protective back from the new label. Place the **CAUTION** label as noted in photo adjacent to the side vented Termination valve. Remove any air bubbles from the label.

NOTE: Do not attempt to remove or adjust the label once it has come into contact with the surface. Doing so may damage the label or cause it not to adhere properly to the surface. IF A LABEL IS DAMAGED OR WILL NOT PROPERLY ADHERE TO THE SURFACE, A NEW LABEL IS REQUIRED.