

## IMPORTANT: SAFETY RECALL REMINDER

In January 2016, we notified you of a Safety Recall involving the bank angle sensor on your 2010-2016 Honda VT750 motorcycle. At the time, we advised owner's of the following:

**Honda has determined that a defect which relates to motor vehicle safety exists in certain 2010-2016 model year Honda VT750C/CA/CS, and VT750C2/C2B/C2F/C2S motorcycles. It is possible that long term exposure to engine vibration may cause the bank angle sensor wiring to break, or be damaged. If the bank angle sensor wiring is damaged or broken, the engine may stall; if this occurs while riding, the risk of a crash will increase.**

**Even if you had your motorcycle's bank angle sensor replaced as part of NHTSA Recall 11V-310, your motorcycle is still affected by this recall and must have a new bank angle sensor installed.**

According to our records, you have not yet had your affected motorcycle repaired. Please call your authorized Honda motorcycle dealer to schedule an appointment as soon as possible. This recall repair will be performed free of charge.

If you have already had your motorcycle repaired, or if you no longer own this motorcycle, please let us know by filling out the included, postage paid, *Information Change Card*. We will update our records and stop sending you reminder notices.

If you have any questions about this recall, your authorized Honda motorcycle dealer will be happy to assist you.

Sincerely,

**American Honda Motor Co., Inc.  
Motorcycle Division**

MTB 15870 (1604)/JW7



NO POSTAGE  
NECESSARY  
IF MAILED  
IN THE  
UNITED STATES