

Toyota Motor North America, Inc.

Vehicle Safety & Compliance  
Liaison Office  
Mail Stop: W4-2D  
6565 Headquarters Drive  
Plano, TX 75024

January 25, 2024

## AMENDMENT TO DEFECT INFORMATION REPORT (15V-284)

The following section of Toyota's Part 573 Report submitted May 13, 2015 is amended to read as follows:

The bolded text in the description of Corrective Repair Action is added as noted below:

### Description of Corrective Repair Action:

All known owners of the affected Toyota vehicles will be notified by first class mail to return their vehicles to a Toyota dealer. The dealer will replace the driver frontal airbag inflator with a newly manufactured one.

**On January 25, 2024, to further urge owners to obtain an urgent and free safety recall repair, Toyota is issuing an immediate DO NOT DRIVE advisory for certain model year 2004-2005 RAV4 vehicles involved in this recall and remain unremedied.**

### Reimbursement Plan for pre-notification remedies

The owner letter will instruct vehicle owners who have paid to have this condition remedied prior to this campaign to seek reimbursement pursuant to Toyota's General Reimbursement Plan.