

Toyota Motor North America, Inc.

Vehicle Safety & Compliance
Liaison Office
Mail Stop: W4-2D
6565 Headquarters Drive
Plano, TX 75024

January 25, 2024

AMENDMENT TO DEFECT INFORMATION REPORT (15V-285)

The following section of Toyota's Part 573 Report submitted May 13, 2015 is amended to read as follows:

The bolded text in the description of Corrective Repair Action is added as noted below:

Description of Corrective Repair Action:

All known owners of the affected Toyota and Lexus vehicles will be notified by first class mail to return their vehicles to a Toyota or Lexus dealer, as applicable. For Corolla and SC430 vehicles, the dealer will replace the front passenger airbag inflator with a newly manufactured one. For Corolla Matrix, the dealer will replace the front passenger airbag assembly with one equipped with a newly specified inflator.

On January 25, 2024, to further urge owners to obtain an urgent and free safety recall repair, Toyota is issuing an immediate DO NOT DRIVE advisory for certain model year 2003-2004 Corolla and 2003-2004 Corolla Matrix vehicles involved in recalls 15V-285 and 15V-043 and both recalls remain unremedied.

General Motors will notify NHTSA separately of its repair and notification schedule.

Reimbursement Plan for pre-notification remedies

The owner letter will instruct vehicle owners who have paid to have this condition remedied prior to this campaign to seek reimbursement pursuant to Toyota's General Reimbursement Plan