



For more information:
Chris Martin (310) 783-3164
Chris_Martin@ahm.honda.com

For Immediate Release

**Statement by American Honda Regarding Plug Top Ignition Coil Recall:
2015 Honda Fit**

TORRANCE, Calif. – Sept. 2, 2015 – Honda will voluntarily recall approximately 17,800 model-year 2015 Fit vehicles in the United States to replace the plug top ignition coils, free of charge. The original plug top ignition coils may degrade over time, which, in the worst case, could cause the vehicle's engine to stall, potentially increasing the risk of a crash. No crashes or injuries have been reported related to this issue, which was discovered through the warranty claim process outside of the United States.

Honda is announcing this recall to encourage each owner of an affected vehicle to take it to an authorized dealer as soon as they receive notification of this recall from Honda. Mailed notification to customers will begin October 6, 2015. Additionally, owners of these vehicles can determine if their vehicles require repair now by going to www.recalls.honda.com or by calling (888) 234-2138.

#