



## SUBJECT

### Delivery Stop – ISOFIX Bracket

## MODEL

F10 (5 Series Sedan)

## SITUATION

A Delivery Stop has been issued on F10 vehicles produced from July 20, 2015 to September 14, 2015. These vehicles may have the rear child seat bracket (anchor) bent, which will prevent the child seat strap from being locked in.

This bulletin will be updated with repair instructions and warranty information when it becomes available.

Please contact your field representatives if you have any questions.

Affected vehicles can be identified with a "Vehicle Comment" in DCS Warranty Vehicle Inquiry or ISPA Light with the description:

**"A Delivery Stop has been issued for this vehicle. Dealers must ensure that all Campaigns are completed before retail delivery to the customer. See Service Information Bulletin B52 09 15."**