

From: [Broadcast Messaging System](#)
To: [DL-BMS Message Monitors](#)
Subject: Delivery Stop: ISOFIX Bracket
Date: Monday, October 26, 2015 5:34:09 PM

Publish Date: October 26, 2015
From: Technical Service
Expiration Date: November 09, 2015

DCSnet Message
Urgent



Subject: **Delivery Stop: ISOFIX Bracket**

Message Recipients: General Managers, Sales Managers, Service and Parts Managers, Service Managers, Shop Foremen, Service Technicians

Message Text:

A Delivery Stop has been issued on 5 Series Sedan (F10) vehicles. These vehicles require inspection of the ISOFIX bracket (child seat latch) and repair if necessary. Refer to attached Service Information bulletin B52 09 15 and Delivery Stop requirement for further information. Please contact your field representatives if you have any questions.

Sincerely, Eugene Aton, Technical Service

Attachments:  [B520915_Delivery_Stop_Legal\[815cc11a\].pdf](#) 
 [B5209152\[815cc119\].pdf](#) 
 [B520915_Delivery_Stop_Legal\[815cc11a\].pdf](#) 
 [B5209152\[815cc119\].pdf](#) 

Recipients: BMW Passenger Cars, All Offerings, All Regions, All Areas, All Departments, All Personnel