

From: [Broadcast Messaging System](#)
To: [DL-BMS Message Monitors](#)
Subject: Updated Delivery Stop: ISOFIX Bracket
Date: Tuesday, October 27, 2015 5:24:26 PM

Publish Date: October 27, 2015
From: Technical Service
Expiration Date: November 10, 2015

DCSnet Message
Urgent



Subject: **Updated Delivery Stop: ISOFIX Bracket**

Message Recipients: General Managers, Sales Managers, Service and Parts Managers, Service Managers, Shop Foremen, Service Technicians

Message Text:

A repair solution is now available for the Delivery Stop that was issued on 5 Series Sedan (F10) vehicles. These vehicles require inspection of the ISOFIX bracket (child seat latch) and repair if necessary. Refer to attached **updated** Service Information bulletin B52 09 15 and Delivery Stop requirement for further information. Please contact your field representatives if you have any questions.

Sincerely, Eugene Aton, Technical Service

Attachments:  [B520915_Delivery_Stop_Legal\[815cb4c1\].pdf](#) 
 [B520915_5\[815cb4c0\].pdf](#) 
 [B520915_Delivery_Stop_Legal\[815cb4c1\].pdf](#) 
 [B520915_5\[815cb4c0\].pdf](#) 

Recipients: BMW Passenger Cars, All Offerings, All Regions, All Areas, All Departments, All Personnel

