

IMPORTANT: SAFETY RECALL REMINDER

In December 2015, we notified you of a Safety Recall involving the drive shaft on your VFR1200F/FD motorcycle. At the time, we advised owners of the following:

Honda has decided that a defect which relates to motor vehicle safety exists in all 2010 and 2012-2013 model year Honda VFR1200F/FD motorcycles. The drive shaft universal joint bearing may not have been properly assembled. An improperly assembled or prematurely worn universal joint bearing may cause the universal joint to separate or break. If the universal joint separates, drive force will be lost; if the universal joint breaks, it may cause the rear wheel to lock while riding. Either outcome increases the risk of a crash.

According to our records, you have not yet had your affected motorcycle repaired. Please call your authorized Honda motorcycle dealer to schedule an appointment as soon as possible. This recall repair will be performed free of charge.

If your motorcycle has already been repaired, or if you no longer own this motorcycle, please let us know by filling out the included, postage paid, *Information Change Card*. We will update our records and stop sending you reminder notices.

If you have any questions about this recall, your authorized Honda motorcycle dealer will be happy to assist you.

Sincerely,

**American Honda Motor Co., Inc.
Motorcycle Division**

MTB 15781 (1602) JW2