



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

August 10, 2016

Mr. John Turley
Honda (American Honda Motor Co.)
1919 Torrance Blvd
Torrance, CA 90501

NEF-150TB
16V-528

Subject: Connecting Rod Bearing Retainer may Fail

Dear Mr. Turley:

This letter serves to acknowledge Honda (American Honda Motor Co.)'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

HONDA/CB300F/2015-2016 HONDA/
CBR300R/2015-2016
HONDA/CBR300RA/2015-2016

Mfr's Report Date: July 8, 2016

NHTSA Campaign Number: 16V-528

Components:

ENGINE AND ENGINE COOLING:ENGINE

Potential Number of Units Affected: 11,424

Problem Description:

Honda (American Honda Motor Co.) is recalling certain model year 2015-2016 CBR300RA, CBR300R and CB300F motorcycles. The affected motorcycles may have an improperly machined crankshaft which may result in the failure of the connecting rod bearing retainer.

Consequence:

If the connecting rod bearing retainer fails, the engine may stall, increasing the risk of a crash.

Remedy:

Honda will notify owners, and dealers will replace the crankshaft assembly, free of charge. The recall is expected to begin August 31, 2016. Owners may contact Honda customer service at 1-866-784-1870. Honda's number for this recall is KB9.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

We have received Honda's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Tariq Bond who may be reached by phone at 1-202-366-5472, or by email at tariq.bond@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,



Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement