

**Recall Quarterly Report****16V-146**

**Manufacturer Name :** Mercedes-Benz USA, LLC.  
**NHTSA Recall No. / MFR Recall No. :** 16V-146 /  
**Recall Subject :** Steering Column Wiring Harness Incorrectly Routed  
**Owner Notification Beginning Date :** APR 22, 2016  
**Owner Notification End Date:** APR 22, 2016



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 6        | OCT 12, 2017    | 2017-3         | 888               | 843            | 0                 | 0             |
| 5        | JUL 18, 2017    | 2017-2         | 888               | 832            | 0                 | 0             |
| 4        | APR 28, 2017    | 2017-1         | 888               | 804            | 0                 | 0             |
| 3        | JAN 10, 2017    | 2016-4         | 888               | 721            | 0                 | 0             |
| 2        | OCT 11, 2016    | 2016-3         | 888               | 613            | 0                 | 0             |
| 1        | JUL 29, 2016    | 2016-2         | 888               | 496            | 0                 | 0             |

This Document Last Updated : OCT 16, 2017

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.