

**Recall Quarterly Report****16V-694**

**Manufacturer Name :** Subaru of America, Inc.  
**NHTSA Recall No. / MFR Recall No. :** 16V-694 /WTK-71  
**Recall Subject :** Windshield Wiper Motor Bottom Cover may Melt  
**Owner Notification Beginning Date :** OCT 25, 2016  
**Owner Notification End Date:** OCT 25, 2016



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
5	JAN 08, 2018	2017-4	592,647	409,664	9,689	0
4	OCT 06, 2017	2017-3	592,647	385,714	9,689	0
3	JUL 14, 2017	2017-2	592,647	357,926	9,689	0
2	APR 12, 2017	2017-1	592,647	317,259	0	0
1	JAN 23, 2017	2016-4	592,647	247,682	0	0

This Document Last Updated : JAN 09, 2018

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.