

**Recall Quarterly Report****16V-738****Manufacturer Name :** Subaru of America, Inc.**NHTSA Recall No. / MFR Recall No. :** 16V-738 /WTM-73**Recall Subject :** Power Relay may Fail Allowing Air Pump to Overheat**Owner Notification Beginning Date :** DEC 16, 2016**Owner Notification End Date:** DEC 16, 2016

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	OCT 06, 2017	2017-3	100,127	49,674	3,801	0
3	JUL 14, 2017	2017-2	100,127	44,092	3,801	0
2	APR 12, 2017	2017-1	100,127	36,259	0	0
1	JAN 23, 2017	2016-4	100,127	15,807	0	0

This Document Last Updated : OCT 10, 2017

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.