

**Recall Quarterly Report****16V-746**

**Manufacturer Name :** BMW of North America, LLC  
**NHTSA Recall No. / MFR Recall No. :** 16V-746 /  
**Recall Subject :** Loose Fuel Pump Wiring may cause Stall/Fuel Leak  
**Owner Notification Beginning Date :** FEB 08, 2017  
**Owner Notification End Date:** FEB 08, 2017



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	APR 22, 2017	2017-1	136,188	1,867	5,809	2,422

This Document Last Updated : MAY 17, 2017

**Definitions :**

- Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).
- Recall Population :** The total number of products recalled by the manufacturer.
- Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.
- Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.
- Total Removed :** Products that have been scrapped, stolen, or exported.