

# Recall Quarterly Report

# 16V-746

**Manufacturer Name :** BMW of North America, LLC

**NHTSA Recall No. / MFR Recall No. :** 16V-746 /

**Recall Subject :** Loose Fuel Pump Wiring may cause Stall/Fuel Leak

**Owner Notification Beginning Date :** FEB 08, 2017

**Owner Notification End Date:** FEB 08, 2017



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 5        | APR 23, 2018    | 2018-1         | 136,188           | 60,589         | 5,809             | 2,677         |
| 4        | JAN 25, 2018    | 2017-4         | 136,188           | 42,875         | 5,809             | 2,672         |
| 3        | OCT 19, 2017    | 2017-3         | 136,188           | 20,672         | 5,809             | 2,587         |
| 2        | JUL 26, 2017    | 2017-2         | 136,188           | 6,505          | 5,809             | 2,563         |
| 1        | APR 22, 2017    | 2017-1         | 136,188           | 1,867          | 5,809             | 2,422         |

This Document Last Updated : APR 25, 2018

## Definitions :

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.