

Part 573 Safety Recall Report**16V-001****Manufacturer Name :** Halcore Group, Inc.**Submission Date :** JAN 04, 2016**NHTSA Recall No. :** 16V-001**Manufacturer Recall No. :** 15E-068**Manufacturer Information :**

Manufacturer Name : Halcore Group, Inc.

Address : 3800 McDowell Road

Grove City OH 43123

Company phone : 999

Population :

Number of potentially involved : 9

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2006-2013 AEV E-Series Wheelchair Van

Vehicle Type : LIGHT VEHICLES

Body Style : VAN

Power Train : NR

Descriptive Information : Under certain conditions present in some applications, the platforms included on the subject S-Series model wheelchair lifts can exhibit cracking of the platform pivot plate while in the stowed position which, if left unchecked, can propagate to the point where separation of the rear portion of the pivot plate occurs rendering the lift potentially inoperable and possibly unsafe for the operator.

Production Dates : JAN 02, 2006 - MAR 15, 2013

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Ricon DOT Public Use, "s" 2000, 5000 and 5500 Series lifts manufactured after January 1, 2006 equipped with platforms measuring 32" x 51" and 34" x 54". Under certain conditions present in some applications, the platforms included on the subject S-Series model wheelchair lifts can exhibit cracking of the platform pivot plate while in the stowed position

FMVSS 1 :NR

FMVSS 2 :NR

Description of the Safety Risk : if left unchecked, can propagate to the point where separation of the rear

portion of the pivot plate occurs rendering the lift potentially inoperable and possibly unsafe for the operators

Description of the Cause : NR
Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Ricon

Address : 1135 Aviation Place
San Fernando CALIFORNIA 91340

Country : United States

Chronology :

NR

Description of Remedy :

Description of Remedy Program : Ricon will provide a field modification instruction and all material required to mitigate this recall at no charge. It will be the responsibility of the lift owners to execute the mitigation.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : JAN 06, 2016 - JAN 08, 2016

* NR - Not Reported