

Part 573 Safety Recall Report**16V-012****Manufacturer Name :** Eldorado National- California, Inc.**Submission Date :** JAN 13, 2016**NHTSA Recall No. :** 16V-012**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Eldorado National- California, Inc.

Address : 9670 GALENA STREET
RIVERSIDE CA 92509

Company phone : 909-591-9557

Population :

Number of potentially involved : 897

Estimated percentage with defect : 10

Vehicle Information :

Vehicle : 2010-2015 Eldorado National CA Axess

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Buses with Recaro ERGO-M commercial bus operators seats

Production Dates : APR 10, 2015 - OCT 14, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2010-2015 Eldorado National CA EZRM

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Buses with Recaro ERGO-M commercial bus operator's seats

Production Dates : APR 10, 2010 - OCT 14, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2011-2015 Eldorado National CA XHF

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Buses with ERGO-M commercial bus operator's seats

Production Dates : JAN 01, 2016 - JAN 08, 2016

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2014-2016 Eldorado National CA Arrivo

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Buses with ERGO-M commercial bus operator's seats

Production Dates : JAN 01, 2014 - JAN 08, 2016

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Certain J-Brackets in the ERGO-M commercial bus operator's seats may be missing welds. As a result, the seatbelt anchorage assembly may separate from the JBracket and the bus driver may not be properly restrained in the event of a crash. There have not been reports of accidents or injuries concerning this issue.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the J-Bracket is missing welds it may separate from the seatbelt anchorage assembly and increase the risk of injury in the event of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Johnson Controls, Inc.

Address : 5757 N. Green Bay Avenue

Milwaukee WISCONSIN 53209

Country : United States

Chronology :

During January 2016 Eldorado National California was sent a letter from Recaro Seats regarding Recall 15E-088

Description of Remedy :

Description of Remedy Program : Johnson Controls will provide the recall remedy. The remedy will consist of an inspection to determine if the appropriate numbers of welds are present

on the J-Bracket. If all five welds are present, no further action is necessary. If the appropriate numbers of welds are not present, the J-Bracket will be removed and replaced

How Remedy Component Differs from Recalled Component : The remedy equipment will consist of a J-Bracket with the correct number of welds (five) present.
Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported