

Part 573 Safety Recall Report**16V-083****Manufacturer Name :** Volkswagen Group of America, Inc.**Submission Date :** FEB 29, 2016**NHTSA Recall No. :** 16V-083**Manufacturer Recall No. :** 69M5**Manufacturer Information :**

Manufacturer Name : Volkswagen Group of America, Inc.

Address : 3800 Hamlin Road

Auburn Hills MI 48326

Company phone : 1-800-893-5298

Population :

Number of potentially involved : 1,037

Estimated percentage with defect : 1

Vehicle Information :

Vehicle : 2009-2009 Volkswagen Routan

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Occupant Restraint Controller (ORC) Module

Production Dates : FEB 07, 2008 - AUG 28, 2008

VIN (Vehicle Identification Number) Range

Begin : 2V8HW34PX9R500006

End : 2V8HW34179R517552

 Not sequential VINs**Description of Defect :**

Description of the Defect : Some Volkswagen Routan vehicles may experience an occupant restraint controller (“ORC”) malfunction resulting in an illuminated airbag warning lamp with the possibility all restraint systems, including airbags, may not deploy in the event of a crash, or an inadvertent air bag deployment without prior illumination of the airbag warning lamp.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the airbag warning lamp is ignored, and the ORC is not replaced, all restraint systems, including the airbags may not deploy in a crash, which could increase the risk of serious injury or death. In the event of an ORC malfunction resulting in inadvertent deployment of the airbags, the risk of a crash and/or injuries could be increased

Description of the Cause : Reference Chrysler Recall (NHTSA 16V047)

Identification of Any Warning that can Occur : The airbag warning lamp will immediately illuminate if the ORC detects a malfunction.

Supplier Identification :

Component Manufacturer

Name : Continental Automotove Systems Inc.

Address : One Continental Drive
Auburn Hills MICHIGAN 48326

Country : United States

Chronology :

February 03, 2016: Volkswagen is informed of Chrysler's recall filing for this issue. Chrysler recall code S07.

Description of Remedy :

Description of Remedy Program : Replace the ORC module.

How Remedy Component Differs from Recalled Component : Not provided by Chrysler

Identify How/When Recall Condition was Corrected in Production : Not provided by Chrysler

Recall Schedule :

Description of Recall Schedule : To be determined

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported