OMB Control No.: 2127-0004

Part 573 Safety Recall Report

16V-083

Manufacturer Name: Volkswagen Group of America, Inc.

Submission Date : FEB 11, 2016 **NHTSA Recall No. :** 16V-083

Manufacturer Recall No.: Not yet assigned



Manufacturer Information:

Manufacturer Name: Volkswagen Group of America, Inc.

Address: 3800 Hamlin Road

Auburn Hills MI 48326 Company phone : 1-800-893-5298

Population:

Number of potentially involved: 1,037 Estimated percentage with defect: 1

Vehicle Information:

Vehicle: 2009-2009 Volkswagen Routan

Vehicle Type:
Body Style:

Power Train: NR

Descriptive Information: Occupant Restraint Controller (ORC) Module

 $Production\ Dates: FEB\ 07,\ 2008\ -\ AUG\ 28,\ 2008$

VIN (Vehicle Identification Number) Range

Begin: 2V8HW34PX9R500006 End: 2V8HW34179R517552 Not sequential VINs

Description of Defect:

Description of the Defect : Some Volkswagen Routan vehicles may experience an occupant restraint controller

("ORC") malfunction resulting in an illuminated airbag warning lamp with the possibility all restraint systems, including airbags, may not deploy in the event of a crash, or an inadvertent air bag deployment without prior illumination of the airbag

warning lamp.

FMVSS 1:NR FMVSS 2:NR

Description of the Safety Risk: If the airbag warning lamp is ignored, and the ORC is not replaced, all restraint

systems, including the airbags may not deploy in a crash, which could increase the risk of serious injury or death. In the event of an ORC malfunction resulting in inadvertent deployment of the airbags, the risk of a crash and/or injuries

could be increased

Description of the Cause: Reference Chrysler Recall (NHTSA 16V047)

Identification of Any Warning that can Occur : The airbag warning lamp will immediately illuminate if the ORC detects a malfunction.

Supplier Identification:

Component Manufacturer

Name: Continental Automotove Systems Inc.

Address: One Continental Drive

Auburn Hills MICHIGAN 48326

Country: United States

Chronology:

February 03, 2016: Volkswagen is informed of Chrysler's recall filing for this issue. Chrysler recall code S07.

Description of Remedy:

Description of Remedy Program : Replace the ORC module.

How Remedy Component Differs from Recalled Component: Not provided by Chrysler

Identify How/When Recall Condition was Corrected in Production: Not provided by Chrysler

Recall Schedule:

Description of Recall Schedule: To be determined

Planned Dealer Notification Date: NR - NR

Planned Owner Notification Date: NR - NR

* NR - Not Reported