

Part 573 Safety Recall Report

16V-165

Manufacturer Name : Weiler, Inc
Submission Date : APR 08, 2016
NHTSA Recall No. : 16V-165
Manufacturer Recall No. : NR

**Manufacturer Information :**

Manufacturer Name : Weiler, Inc
Address : 815 Weiler Drive
 Knoxville IA 50138
Company phone : 641-828-6622

Population :

Number of potentially involved : 380
Estimated percentage with defect : 64 %

Vehicle Information :

Vehicle 1 : 2004-2008 Housby B2

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : Truck bodies

Production Dates : AUG 25, 2004 - OCT 23, 2008

VIN Range 1 : Begin : 1M2AG02C05M002365 End : 4V5KC9GF97N458633 Not sequential

Vehicle 2 : 2012-2015 Housby B3

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : Truck bodies.

Production Dates : AUG 09, 2013 - APR 07, 2015

VIN Range 1 : Begin : 1M2AX04C1FM022378 End : 1M2AX07CXDM016703 Not sequential

Vehicle 3 : 2012-2016 Housby B5

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : Truck bodies

Production Dates : MAY 09, 2012 - MAR 17, 2016

VIN Range 1 : Begin : 1M2AX04C0GM027394 End : 1NPTL7EXXDD182736 Not sequential

Vehicle 4 : 2003-2006 Housby F1

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : Truck bodies

Production Dates : APR 08, 2003 - DEC 18, 2006

VIN Range 1 : Begin : 1M2AG03C22M001230 End : 1NKDL00X26J157763 Not sequential

Vehicle 5 : 2006-2015 Housby F3

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : Truck bodies

Production Dates : NOV 08, 2006 - NOV 30, 2015

VIN Range 1 : Begin : 1M2AG11C07M067954 End : 1NPALOEX55D837109 Not sequential

Vehicle 6 : 2015-2015 Housby F5

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : Truck bodies

Production Dates : AUG 07, 2015 - DEC 15, 2015

VIN Range 1 : Begin : 1M2AX13C2GM033463 End : 3HAGSSNT8GL407774 Not sequential

Vehicle 7 : 2014-2014 Weiler M100

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : Truck bodies

Production Dates : AUG 12, 2014 - SEP 24, 2014

VIN Range 1 : Begin : 1NKZL70X3FJ447086 End : 1NKZLPOX1EJ417549 Not sequential

Vehicle 8 : 2014-2014 Weiler M200

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : Truck bodies

Production Dates : SEP 30, 2014 - SEP 30, 2014

VIN Range 1 : Begin : 3HTKATKT9FN563503 End : 3HTKATKT9FN563503 Not sequential

Description of Noncompliance :

Description of the Noncompliance : These truck models have LED marker lights which do not have reflectors built into the lenses, reducing the visibility of the vehicle. As such, these vehicles do not comply with the requirements of the Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment."

FMVSS 1 : 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2 : NR

Description of the Safety Risk : The absence of reflectors could reduce the visibility for others to see the vehicle, increasing the risk of a crash.

Description of the Cause : During manufacturing, the side marker lights and rear marker lights installed on identified machines did not contain a reflective material as required by government regulation FMVSS 108 for United States, Canada, and Mexico.

Identification of Any Warning that can Occur : If the machine is on a public roadway at night or with limited sunlight, death or serious injury is possible if the side or rear of the machine is not seen by drivers of other vehicles, and another vehicle strikes the machine. Property or truck damage is also possible.

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

On March 16, 2016, Product Safety at Weiler, Inc., confirmed that there is a noncompliance with the LED lighting on its truck bodies, primarily cement mixers.

Description of Remedy :

Description of Remedy Program : Weiler will notify owners and dealer, and will supply reflective decals to be installed on the vehicles, free of charge.

How Remedy Component Differs from Recalled Component : Self-adhesive reflex reflectors will be added to the machines.

Identify How/When Recall Condition was Corrected in Production : Self-adhesive reflex reflectors added to the machines.

Recall Schedule :

Description of Recall Schedule : TBD

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported