

Part 573 Safety Recall Report**16V-187****Manufacturer Name :** Jaguar Land Rover North America, LLC**Submission Date :** MAR 31, 2016**NHTSA Recall No. :** 16V-187**Manufacturer Recall No. :** J059**Manufacturer Information :**

Manufacturer Name : Jaguar Land Rover North America, LLC

Address : 555 MACARTHUR BOLULEVARD

MAHWAH NJ 07430

Company phone : 201-760-8534

Population :

Number of potentially involved : 28

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2010-2010 JAGUAR XF

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : 2010 MY Jaguar XF Vehicles in select VIN range

Production Dates : DEC 17, 2008 - APR 15, 2009

VIN (Vehicle Identification Number) Range

Begin : SAJWA0HB1ALR43674

End : SAJWA0GB3ALR46304

 Not sequential VINs**Description of Defect :**

Description of the Defect : Customers have reported fuel odor, the amber Malfunction Indicator Lamp on the Instrument Cluster illuminating and or liquid fuel on the ground. On investigation, dealer technicians are finding that the fuel outlet flange mounted in the fuel tank is cracked.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The driver may also experience fuel odor and in some circumstances, with the vehicle static, there could be liquid fuel underneath the rear of the vehicle, which in the presence of an ignition source could lead to a fire.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Continental Teves Czech Republic, s.r.o.

Address : Prumyslova 2299

Brandys nad Labem FOREIGN STATES 250 01

Country : Czech Republic

Chronology :

See Document "JLR J059 Chronology".

Description of Remedy :

Description of Remedy Program : Owners will be notified and instructed to take their vehicles to a Jaguar authorized repairer to have the fuel outlet mounting flange replaced with a component of revised design.

There will be no charge to owners for this repair.

Customers who have paid for a repair of this defect will be subject to the Jaguar Land Rover reimbursement plan subject to terms and conditions.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Distribution of owner notification letters will occur on or before May 20, 2016.
Notifications to dealers will occur on April 5, 2016.

Planned Dealer Notification Date : APR 05, 2016 - APR 05, 2016

Planned Owner Notification Date : MAY 20, 2016 - MAY 20, 2016

* NR - Not Reported