

Part 573 Safety Recall Report**16V-207****Manufacturer Name :** Daimler Trucks North America LLC**Submission Date :** APR 08, 2016**NHTSA Recall No. :** 16V-207**Manufacturer Recall No. :** FL-706**Manufacturer Information :**

Manufacturer Name : Daimler Trucks North America LLC

Address : 4747 N. Channel Avenue

Portland OR 97217-3849

Company phone : 800-745-8000

Population :

Number of potentially involved : 4

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2016-2016 Freightliner 114SD

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Vehicles with Bridgestone R249 front tires with 20k front axle weight ratings

Production Dates : JUN 10, 2015 - OCT 01, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2016-2016 Freightliner M2 Business Class

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Vehicles with Bridgestone R249 front tires with 20k front axle weight ratings

Production Dates : JUN 10, 2015 - OCT 01, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : The front tires on the affected vehicles have a lower maximum load capacity than the maximum specified front axle capacity of the vehicle.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The customer may not be aware of this reduced load capacity. If the tires are

overloaded, there is an increased potential risk of tire failure which could lead to a vehicle crash.

Description of the Cause : NR
Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

Date Fact or Event

February 2016 DTNA became aware of a potential tire specification issue.

February 2016 through April 2016 DTNA investigated the issue.

April 2016 DTNA decided to initiate a voluntary recall campaign.

Description of Remedy :

Description of Remedy Program : The tires on the front axle will be replaced with tires of a higher load capacity. Repairs will be performed by Daimler Trucks North America authorized service facilities. Copies of the reimbursement plan will be submitted as a supplemental report when available.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Customer notification will be made by first class mail using Daimler Trucks North America records to determine the customers affected.

Planned Dealer Notification Date : JUN 07, 2016 - JUN 07, 2016

Planned Owner Notification Date : JUN 07, 2016 - JUN 07, 2016

* NR - Not Reported