

# Part 573 Safety Recall Report

# 16V-277

**Manufacturer Name :** Winnebago Industries, Inc**Submission Date :** JUN 20, 2016**NHTSA Recall No. :** 16V-277**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Winnebago Industries, Inc

Address : PO BOX 152  
605 W. Crystal Lake Rd. Forest City IA  
50436

Company phone : 1-641-585-3535

**Population :**

Number of potentially involved : 91

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2016-2016 Winnebago Journey

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Daimler Sway Bar recall FL-707 / 16V-208

Production Dates : MAY 07, 2015 - MAR 25, 2016

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 2 : 2016-2016 Winnebago Forza

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Daimler Sway Bar recall FL-707 / 16V-208

Production Dates : MAY 07, 2015 - MAR 25, 2016

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 3 : 2016-2016 Itasca Solei

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Daimler Sway Bar recall FL-707 / 16V-208

Production Dates : MAY 07, 2015 - MAR 25, 2016

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 4 : 2016-2016 Itasca Meridan

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Daimler Sway Bar recall FL-707 / 16V-208

Production Dates : MAY 07, 2015 - MAR 25, 2016

VIN Range 1 : Begin : NR End : NR

Not sequential

## Description of Defect :

Description of the Defect : The front sway bar mounting may not fit flush on the axle mounting surface and cause the mounting bolts to bend or become loose

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Loose sway bar mounting bolts could potentially result in a detached sway bar. A detached sway bar on a motor home may result in higher than expected vehicle sway or reduced handling potentially increasing the risk of a crash

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

## Supplier Identification :

### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

## Chronology :

5-2-16 Received e-mail from Daimler on their recall FL-707

5-2-16 ran report put the two units we had in house on hold, let Daimler know we had a current list of addresses for the affected VINs.

5-3-16 made attempts to input 573 letter to portal ( could not logo on due to maintenance or heavy traffic )

5-4-16 Winnebago Internet was down

5-6-16 Attempting again to input this recall to NHTSA portal

**Description of Remedy :**

Description of Remedy Program : The sway bar mounting will be modified on affected vehicles. Repairs will be performed by Daimler Trucks North America authorized service facilities. Daimler will submit reimbursement plan when available ref: NHTSA 16V-208

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

\* NR - Not Reported