

**Part 573 Safety Recall Report****16V-314****Manufacturer Name :** Stoughton Trailers, LLC**Submission Date :** MAY 11, 2016**NHTSA Recall No. :** 16V-314**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Stoughton Trailers, LLC

Address : 416 South Academy Street  
Stoughton WI 53589-0606

Company phone : 608-873-2500

**Population :**

Number of potentially involved : 1,205

Estimated percentage with defect : 100

**Vehicle Information :**

Vehicle : 2014-2014 STOUGHTON AVH

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : SAF HOLLAND PIVOT BOLT DEFECT

Production Dates : NOV 05, 2013 - NOV 21, 2013

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2014-2014 STOUGHTON ZGPVW

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : SAF HOLLAND PIVOT BOLT DEFECT

Production Dates : OCT 01, 2013 - DEC 17, 2013

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2014-2014 STOUGHTON AVXW

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : SAF HOLLAND PIVOT BOLT DEFECT

Production Dates : OCT 01, 2013 - DEC 16, 2013

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

Not sequential VINs

Vehicle : 2014-2014 STOUGHTON AVW

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : SAF HOLLAND PIVOT BOLT DEFECT

Production Dates : OCT 01, 2013 - DEC 16, 2013

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

Not sequential VINs

**Description of Defect :**

Description of the Defect : Stoughton Trailers, LLC (Stoughton) is expanding recall 14V-268 to include 2014 AVW trailers manufactured October 1, 2013, through December 18, 2013, AVXW trailers manufactured December 3, 2013, through December 16, 2013, ZGPVW trailers manufactured October 1, 2013, through December 17, 2013, and AHV trailers manufactured November 5, 2013, through November 21, 2013, and equipped with certain SAF-Holland-brand CBX Trailer Suspension Air Ride Axle Systems. The affected trailer suspensions have pivot bolts that may fail.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Failure of the pivot bolts may cause the suspension and attached axle to separate from the trailer, increasing the risk of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

**Supplier Identification :**

**Component Manufacturer**

Name : SAF Holland

Address : NR

NR

Country : NR

**Chronology :**

Stoughton Trailers was notified by SAF Holland of the safety defect recall on April, 18 2016

**Description of Remedy :**

Description of Remedy Program : Stoughton will notify owners, and SAF-Holland-approved repair shops will replace the defective pivot bolts with new pivot bolts, free of charge. The recall is expected to begin by late May 2016. Owners may contact Stoughton customer service at 1-608-873-2555, or SAF-Holland customer service at 1-888-396-6501.

How Remedy Component Differs from Recalled Component : There is a white dot applied to the head of the  
remedy pivot bolt

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : MAY 27, 2016 - JUN 24, 2016

Planned Owner Notification Date : JUN 03, 2016 - JUL 01, 2016

\* NR - Not Reported