

Part 573 Safety Recall Report

16V-351

Manufacturer Name : Daimler Vans USA, LLC**Submission Date :** MAY 17, 2016**NHTSA Recall No. :** 16V-351**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Daimler Vans USA, LLC

Address : 303Perimeter Center North
Suite 202 Atlanta GA 30346

Company phone : 7707052070

Population :

Number of potentially involved : 3

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2015-2016 Mercedes Benz Sprinter

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : VAN

Power Train : DIESEL

Descriptive Information : Daimler AG, the manufacturer of Mercedes-Benz and Freightliner Sprinter vehicles, has determined that certain vehicles with the super-high roof are not equipped with crash-pads.

Production Dates : MAY 31, 2015 - APR 30, 2016

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 2 : 2015-2016 Freightliner Sprinter

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : VAN

Power Train : DIESEL

Descriptive Information : Daimler AG, the manufacturer of Mercedes-Benz and Freightliner Sprinter vehicles, has determined that certain vehicles with the super-high roof are not equipped with crash-pads.

Production Dates : MAY 01, 2015 - APR 30, 2016

VIN Range 1 : Begin : NR End : NR

 Not sequential**Description of Defect :**

Description of the Defect : Daimler AG, the manufacturer of Mercedes-Benz and Freightliner Sprinter vehicles, has determined that certain vehicles with the super-high roof are not equipped with crash-pads.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : In the event of a crash t the risk of injury might be increased for an unbelted occupant in the front passenger seat area.

Description of the Cause : Due to a change in the documentation process the affected vehicles were built and delivered without the required crash-pads.

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR
NR

Country : NR

Chronology :

In April 2016, DAG was made aware of this issue based on internal process monitoring of the vehicle production.

As of today, DAG is not aware of any complaint or incident on any of the affected vehicles.

Description of Remedy :

Description of Remedy Program : DVUSA will conduct a voluntary recall in order to equip the affected vehicles with the required crash-pads. Pursuant to 49 C.F.R. § 577.11(e), DVUSA does not plan to provide notice regarding pre-notice reimbursement to owners since all involved vehicles remain covered under the new vehicle warranty.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : The range of affected vehicles has been clearly defined by production date.

Recall Schedule :

Description of Recall Schedule : Dealers are expected to be notified in May 2016. A copy of all communications will be provided when available.
Owners are expected to be notified in May 2016, one week after recall launch to the dealers.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported