

Part 573 Safety Recall Report

16V-363

Manufacturer Name : Mercedes-Benz USA, LLC.

Submission Date : NOV 11, 2019

NHTSA Recall No. : 16V-363

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Mercedes-Benz USA, LLC.

Address : 13470 International Parkway
Jacksonville FL 32218

Company phone : 1-877-496-3691

Population :

Number of potentially involved : 199,705

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2010-2011 Mercedes-Benz C300 Sedan

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : 204.054 GF5E 48,706 vehicles

Production Dates : AUG 01, 2009 - AUG 01, 2011

VIN Range 1 : Begin : NR End : NR ☐ Not sequential

Vehicle 2 : 2011-2011 Mercedes-Benz E550 Convertible

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : 207.472 KK7C 1,465 vehicles

Production Dates : AUG 01, 2010 - AUG 31, 2011

VIN Range 1 : Begin : NR End : NR ☐ Not sequential

Vehicle 3 : 2008-2009 Mercedes-Benz C350 Sedan

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : 204.056 GF56 18,129 vehicles

Production Dates : AUG 01, 2007 - AUG 01, 2009

VIN Range 1 : Begin : NR End : NR ☐ Not sequential

Vehicle 4 : 2010-2011 Mercedes-Benz C350 Sedan

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : 204.056 GF5G 2,911 vehicles

Production Dates : AUG 01, 2009 - AUG 01, 2011

VIN Range 1 : Begin : NR End : NR

☐ Not sequential

Vehicle 5 : 2008-2009 Mercedes-Benz C63 AMG Sedan

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : 204.077 GF77 1,576 vehicles

Production Dates : AUG 01, 2007 - AUG 01, 2009

VIN Range 1 : Begin : NR End : NR

☐ Not sequential

Vehicle 6 : 2010-2011 Mercedes-Benz C63 AMG Sedan

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : 204.077 GF7H 794 vehicles

Production Dates : AUG 01, 2009 - AUG 01, 2011

VIN Range 1 : Begin : NR End : NR

☐ Not sequential

Vehicle 7 : 2008-2009 Mercedes-Benz C300 4-Matic Sedan

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : 204.081 GF81 16,336 vehicles

Production Dates : AUG 01, 2007 - AUG 01, 2009

VIN Range 1 : Begin : NR End : NR

☐ Not sequential

Vehicle 8 : 2010-2011 Mercedes-Benz C300 4-Matic Sedan

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : 204.081 GF8B 7,023 vehicles

Production Dates : AUG 01, 2009 - AUG 01, 2011

VIN Range 1 : Begin : NR End : NR

☐ Not sequential

Vehicle 9 : 2010-2011 Mercedes-Benz GLK 350W2

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : 204.956 GG5G 17,239 vehicles

Production Dates : AUG 01, 2009 - AUG 01, 2011

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 10 : 2010-2011 Mercedes-Benz GLK 350 4-Matic

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : 204.987 GG8G 9,707 vehicles

Production Dates : AUG 01, 2009 - AUG 01, 2011

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 11 : 2011-2011 Mercedes-Benz SLS AMG

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : 197.377 RJ7H 496 vehicles

Production Dates : AUG 01, 2010 - AUG 31, 2011

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 12 : 2010-2011 Mercedes-Benz E350 Coupe

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : 207.356 KJ5G 7,294 vehicles

Production Dates : AUG 01, 2009 - AUG 31, 2011

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 13 : 2011-2011 Mercedes-Benz E550 Coupe

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : 207.372 KJ7C 2,315 vehicles

Production Dates : AUG 01, 2010 - AUG 31, 2011

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 14 : 2011-2011 Mercedes-Benz E350 Convertible

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : 207.456 KK5G 3,815 vehicles

Production Dates : AUG 01, 2010 - AUG 02, 2011

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 15 : 2008-2009 Mercedes-Benz C300 Sedan

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : 204.054 GF54 61803 vehicles

Production Dates : AUG 01, 2007 - AUG 01, 2009

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Description of Defect :

Description of the Defect : Updated Nov 11, 2019 - This submission is to inform of MBUSA's intent to implement the "other" reporting category for removed vehicles in Quarterly Reporting as permitted in the Third Amendment to the Coordinated Remedy Order ("ACRO"), Paragraphs 45 through 49. As a condition of the ACRO, all affected vehicles will remain active, or "live", across MBUSA's data systems such that any search of "other" removed VINs will return an "open" recall status and for this reason, the population figure in this recall will remain the same. Future changes to overall Total Removed counts, including "Other", will be reflected in quarterly reporting for this recall. Certain Mercedes-Benz vehicles are equipped with passenger-side front airbags provided by the supplier TK Holdings Inc. ("Takata"). On May 16, 2016 Takata filed a Defect Information Report with NHTSA announcing a potential defect in some of the subject inflators. Based upon Takata's information to date, "Takata is not aware of any test ruptures in ballistic testing or confirmed field incidents of the subject non-desiccated ammonium nitrate inflators other than those already under recall as detailed in prior defect information reports. Out of an abundance of caution, however, Takata is filing this report in cooperation with NHTSA to promote public safety."

Daimler AG ("DAG") is not aware of any field incidents with the subject Takata PSPI-2 inflators. However, based on the information above and out of an abundance of caution, DAG will conduct a voluntary recall of the vehicles equipped with the subject Takata PSPI-2 inflators in zones A, B, and C (no affected vehicles in Zone C) in the United States as identified by Takata in the Defect Information Report.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : According to Takata, in the event of an inflator rupture, metal fragments could pass through the air bag cushion material, which may result in injury or death to vehicle occupants.

Description of the Cause : According to Takata, "... a defect related to motor vehicle safety may arise in some of the subject ammonium nitrate inflators due to propellant degradation occurring after prolonged exposure to high absolute humidity, high temperatures and high temperature cycling. Testing and analyses conducted by Takata and by independent entities have found that there are wide differences in the time periods in which propellant degradation takes place. The

Identification of Any Warning
that can Occur :

propellant degradation varies in different climate zones, in different vehicle makes and models, and in different inflator and propellant configurations. Takata believes that the subject inflators perform as originally designed and manufactured and do not pose an unreasonable risk to safety until they reach a certain level of propellant degradation.”

Supplier Identification :**Component Manufacturer**

Name : TK Holding
Address : NR
FOREIGN STATES
Country : Japan

Chronology :

On October 14, 2015, Daimler submitted the response to a NHTSA inquiry, including the number of all US-vehicles equipped with Takata PSPI-2 inflators. NHTSA released a press statement on May 4, 2016, regarding the recall of estimated 35-40 million inflators. These inflators are included in US-vehicles of various manufacturers, including Mercedes-Benz. On May 16, 2016, Takata submitted a Defect Information Report to NHTSA including their PSPI-2-inflators. On May 19, 2016 DAG decided to recall all Zone A & B vehicles with the subject Takata PSPI-2 inflators as identified by Takata. This step is taken by DAG as a reaction to Takata's filing of the Defect Information Report and out of an abundance of caution.

Description of Remedy :

Description of Remedy Program : Authorized Mercedes-Benz dealers will replace the passenger-side front airbag modules in the potentially affected Mercedes-Benz vehicles. Mercedes-Benz USA will provide notice regarding pre-notice reimbursement to owners in the customer letter.

How Remedy Component Differs
from Recalled Component :

NR

Identify How/When Recall Condition
was Corrected in Production :

NR

Recall Schedule :

Description of Recall Schedule :	Owners will be notified with an interim letter starting in approximately July, 2016. Dealers will be notified of the pending voluntary recall campaign in approximately June 2016. A copy of all communications will be provided when available.
Planned Dealer Notification Date :	NR - NR
Planned Owner Notification Date :	NR - NR

* NR - Not Reported