

# Part 573 Safety Recall Report

# 16V-462

**Manufacturer Name :** Entegra Coach

**Submission Date :** JUN 22, 2016

**NHTSA Recall No. :** 16V-462

**Manufacturer Recall No. :** not applicable



## Manufacturer Information :

**Manufacturer Name :** Entegra Coach

**Address :** 903 South Main Street

P.O. Box 460 Middlebury IN 46540

**Company phone :** 1-800-945-4787

## Population :

**Number of potentially involved :** 30

**Estimated percentage with defect :** 100 %

## Vehicle Information :

**Vehicle 1 :** 2015-2016 Class A Motor Home Aspire and Aspire TK

**Vehicle Type :** BUSES, MEDIUM & HEAVY VEHICLES

**Body Style :**

**Power Train :** NR

**Descriptive Information :** 2015 Aspire TK 39E F12E8051-8061

2015 Aspire TK 38M F12M8051-8060

2016 Aspire 39S G13S8051-8056

**Production Dates :** JUL 14, 2014 - JAN 15, 2016

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

## Description of Defect :

**Description of the Defect :** Per Daimler Recall 16V321 on certain motor home chassis, when the throttle pedal is released the associated pedal sensor may not return to zero, causing the engine brake to potentially not activate as expected.

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** Per Daimler - A sudden loss of an engine brake without warning on a motorhome may lead to reduced brake capacity potentially increasing the risk of a vehicle crash.

**Description of the Cause :** NR

**Identification of Any Warning that can Occur :** NR

**Supplier Identification :****Component Manufacturer**

Name : Daimler Truck  
Address : NR  
NR  
Country : United States

**Chronology :**

Entegra is filing this recall information ONLY to note the affected Entegra product under a recall number posted. Current owner information was provided to Daimler for their official release. Daimler is releasing the recall letter, scheduling repairs at Daimler Service Centers, submit eh required quarterly reports to NHTSA.

**Description of Remedy :**

Description of Remedy Program : Per Daimler - Throttle pedal will be replacec  
How Remedy Component Differs NR  
from Recalled Component :  
Identify How/When Recall Condition NR  
was Corrected in Production :

**Recall Schedule :**

Description of Recall Schedule : Per Daimler - they plan to release 7-10-2016  
Planned Dealer Notification Date : NR - NR  
Planned Owner Notification Date : NR - NR

\* NR - Not Reported