

Part 573 Safety Recall Report

16V-463

Manufacturer Name : Entegra Coach

Submission Date : JUN 22, 2016

NHTSA Recall No. : 16V-463

Manufacturer Recall No. : not applicable



Manufacturer Information :

Population :

Manufacturer Name : Entegra Coach

Number of potentially involved : 30

Address : 903 South Main Street

Estimated percentage with defect : 100 %

P.O. Box 460 Middlebury IN 46540

Company phone : 1-800-945-4787

Vehicle Information :

Vehicle 1 : 2015-2016 Class A Motor Home Aspire and Aspire TK

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : 2015 Aspire TK F12E8051-8061 and Aspire F12M8051-8060
2016 Aspire G13S8051-8059

Production Dates : JUL 14, 2014 - JAN 15, 2016

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : Per Daimler on behalf of Freightliner Customer Chassis Recall 16V204 - certain motorhome chassis equipped with a certain adjustable foot pedal, the brake activation signal to the brake lights and to certain towed devices may not deactivate when the motorhome service brakes are relapsed.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : May cause the motorhome brake lights to potentially remain illuminated, and additionally may cause the brakes on the towed device to remain engaged, depending on brake configuration. A towed device with incorrectly operation brakes could increase the risk of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Daimler Trucks
Address : NR
NR
Country : United States

Chronology :

Entegra is filing this recall information only to note the affected Entegra product under a recall number posted for Entegra. Current Owner information was provided to Daimler for their official release. Daimler is releasing the recall letter, scheduling repairs at Daimler Service Center, submitting the required quarterly reports to NHTSA.

Description of Remedy :

Description of Remedy Program : Per Daimler recall 16V204 - a new torsion spring will be added to the pedal assembly to improve the pedal return by Daimler

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Entegra is NOT releasing this recall. Daimler is releasing FL704A under 16V-204

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported