

Part 573 Safety Recall Report

16V-468

Manufacturer Name : Thor Motor Coach**Submission Date :** JUN 23, 2016**NHTSA Recall No. :** 16V-468**Manufacturer Recall No. :** RC000117**Manufacturer Information :****Population :**

Manufacturer Name : Thor Motor Coach

Number of potentially involved : 122

Address : PO Box 1486

Estimated percentage with defect : 100 %

701 County Road 15 Elkhart IN 46516

Company phone : 877-500-1020

Vehicle Information :

Vehicle 1 : 2016-2016 Thor Motor Coach Tuscany XTE

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : Thor Motor Coach Motorhome

Production Dates : SEP 09, 2015 - JAN 12, 2016

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 2 : 2016-2016 Thor Motor Coach Palazzo

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : Thor Motor Coach Motorhome

Production Dates : SEP 09, 2015 - JAN 12, 2016

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 3 : 2016-2017 Thor Motor Coach Venetian

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : Thor Motor Coach Motorhome

Production Dates : SEP 09, 2015 - JAN 12, 2016

VIN Range 1 : Begin : NR End : NR

 Not sequential**Description of Defect :**

Description of the Defect : On certain motorhome chassis the front sway bar mounting bracket may not fit flush on the axle mounting surface, causing the mounting bolts to bend or loosen.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Loose mounting fasteners could cause the sway bar to detach, resulting in higher than expected vehicle sway or reduced handling increasing the possibility of a crash.

Description of the Cause : The mounting bracket was installed improperly.

Identification of Any Warning that can Occur : None

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

June 2016 - DTNA notified Thor Industries of their recall 16V-208.

Description of Remedy :

Description of Remedy Program : DTNA will modify the sway bar mounting. Repairs will be performed by Detroit Axle authorized service centers.

How Remedy Component Differs from Recalled Component : NA

Identify How/When Recall Condition was Corrected in Production : NA

Recall Schedule :

Description of Recall Schedule : TMC will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported