

Part 573 Safety Recall Report

16V-478

Manufacturer Name : Newmar Corporation**Submission Date :** JUN 24, 2016**NHTSA Recall No. :** 16V-478**Manufacturer Recall No. :** 16V 321**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Population :

Number of potentially involved : 1,243

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2014-2016 Newmar Dutch Star

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, when the throttle pedal is released, the associated pedal sensor may not return to zero, causing the engine brake to potentially not activate as expended. A sudden loss of an engine brake without warning on a motorhome may lead to a reduced brake capacity potentially increasing the risk of a vehicle crash. Correction: The throttle pedal will be replaced. Repairs will be performed by Daimler Trucks North America authorized service facilities.

Production Dates : JAN 28, 2013 - DEC 14, 2015

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2014-2016 Newmar Mountain Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, when the throttle pedal is released, the associated pedal sensor may not return to zero, causing the engine brake to potentially not activate as expended. A sudden loss of an engine brake without warning on a motorhome may lead to a reduced brake capacity potentially increasing the risk of a vehicle crash. Correction: The throttle pedal will be replaced. Repairs will be performed by Daimler Trucks North America authorized service facilities.

Production Dates : JAN 28, 2013 - DEC 14, 2015

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 3 : 2015-2016 Newmar London Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, when the throttle pedal is released, the associated pedal sensor may not return to zero, causing the engine brake to potentially not activate as expended. A sudden loss of an engine brake without warning on a motorhome may lead to a reduced brake capacity potentially increasing the risk of a vehicle crash.
Correction: The throttle pedal will be replaced. Repairs will be performed by Daimler Trucks North America authorized service facilities.

Production Dates : JAN 28, 2013 - DEC 14, 2015

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 4 : 2015-2016 Newmar Essex

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, when the throttle pedal is released, the associated pedal sensor may not return to zero, causing the engine brake to potentially not activate as expended. A sudden loss of an engine brake without warning on a motorhome may lead to a reduced brake capacity potentially increasing the risk of a vehicle crash.
Correction: The throttle pedal will be replaced. Repairs will be performed by Daimler Trucks North America authorized service facilities.

Production Dates : JAN 28, 2013 - DEC 14, 2015

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : On certain motorhomes, when the throttle pedal is released, the associated pedal sensor may not return to zero, causing the engine brake to potentially not activate as expended. A sudden loss of an engine brake without warning on a motorhome may lead to a reduced brake capacity potentially increasing the risk of a vehicle crash.

Correction: The throttle pedal will be replaced. Repairs will be performed by Daimler Trucks North America authorized service facilities.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : A sudden loss of an engine brake without warning on a motorhome may lead to a reduced brake capacity potentially increasing the risk of a vehicle crash.

Description of the Cause : NR

Identification of Any Warning NR
that can Occur :

Supplier Identification :

Component Manufacturer

Name : NR
Address : NR
NR
Country : NR

Chronology :

June, 2016 Newmar was given notice by Daimler Trucks North America of a potential defect for pedal assemblies, June, 2016 Newmar is giving notice of recall.

Description of Remedy :

Description of Remedy Program : NR
How Remedy Component Differs NR
from Recalled Component :
Identify How/When Recall Condition NR
was Corrected in Production :

Recall Schedule :

Description of Recall Schedule : NR
Planned Dealer Notification Date : AUG 23, 2016 - AUG 23, 2016
Planned Owner Notification Date : AUG 23, 2016 - AUG 23, 2016

* NR - Not Reported