#### OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

## 16V-529

**Manufacturer Name:** Chrysler (FCA US LLC)

NHTSA Recall No.: 16V-529

Manufacturer Recall No.: S55



#### **Manufacturer Information:**

Manufacturer Name: Chrysler (FCA US LLC)

Address: 800 Chrysler Drive

CIMS 482-00-91 Auburn Hills MI

48326-2757

Company phone: 1-800-853-1403

## **Population:**

Number of potentially involved: 412,981 Estimated percentage with defect: 5 %

#### **Vehicle Information:**

Vehicle 1: 2014-2015 Jeep Cherokee

Vehicle Type : Body Style : SUV

Power Train: NR

Descriptive Information: Certain 2014 and 2015 Jeep Cherokee ("KL") vehicles equipped with either the 9HP48

or 948TE transmission.

Production Dates: NOV 05, 2012 - OCT 31, 2014

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 2: 2015-2015 RAM ProMaster City

Vehicle Type:

Body Style: VAN Power Train: NR

Descriptive Information: Certain 2015 Ram ProMaster City ("VM") vehicles equipped with the 9HP48 or 948TE

transmission.

Production Dates: SEP 10, 2014 - AUG 24, 2015

Vehicle 3: 2016-2016 Fiat 500X

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: Certain 2016 Fiat 500X ("FB") vehicles equipped with either the 9HP48 or 948TE

transmission.

Production Dates: MAY 29, 2014 - JUL 29, 2015

VIN Range 1 : Begin : NR End : NR Not sequential

Not sequential

Vehicle 4: 2015-2015 Chrysler 200

Vehicle Type:

Body Style : 4-DOOR Power Train : NR

Descriptive Information: Certain 2015 Chrysler 200 ("UF") vehicles equipped with the 9HP48 or 948TE

transmission.

Production Dates: NOV 05, 2012 - OCT 31, 2014

VIN Range 1 : Begin : NR End : NR

Vehicle 5: 2015-2015 Jeep Renegade

Vehicle Type:

Body Style: SUV Power Train: NR

Descriptive Information : Certain 2015 Jeep Renegade ("BU") vehicles equipped with the 9HP48 or 948TE

transmission.

Production Dates: DEC 09, 2014 - SEP 23, 2015

## **Description of Defect:**

Description of the Defect: Some Jeep Cherokee ("KL"), Jeep Renegade ("BU"), Chrysler 200 ("UF"), and

Ram ProMaster City ("VM") vehicles may have insufficient crimps in the transmission wire harness that may cause an unexpected shift to neutral

resulting in a sudden loss of motive power.

FMVSS 1: NR

FMVSS 2: NR

Description of the Safety Risk: The customer may experience a sudden loss of motive power.

Description of the Cause: NR

Identification of Any Warning NR

that can Occur:

### **Supplier Identification:**

## **Component Manufacturer**

Name: KE Elektronik GmbH Address: Im Klingenfeld 21

Kressberg Marktlustenau FOREIGN STATES 74594

Country: Germany

## **Chronology:**

Please see the attached supplemental information titled "FCA US LLC Chronology – 9-Speed Harness Crimp – 07122016.pdf".

## **Description of Remedy:**

Description of Remedy Program: FCA US will reprogram the Powertrain Control Module ("PCM") and the

Transmission Control Module ("TCM"). In addition, if the vehicle has an active or stored fault code, the transaxle range sensor wire harness will be

replaced.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

#### **Recall Schedule:**

Description of Recall Schedule: \*\*2016 10 06 - For Cherokee, 200, and Pro Master City, Dealer

Notification is planned for 10/20/2016, and Owner notification is

10/27/2016.

\*\* 2016 8 31: Planned Dealer Notification 9/1/2016, Planned Owner

Notification 9/6/2016.

2016 07 25 - Planned Dealer Notification: 8/19/2016. Planned Owner

**Notification: 8/26/2016** 

FCA US will provide a dealer notification and owner notification schedule

once established.

Planned Dealer Notification Date: NR - NR

Planned Owner Notification Date: NR - NR

<sup>\*</sup> NR - Not Reported