

# Part 573 Safety Recall Report

# 16V-529

**Manufacturer Name :** Chrysler (FCA US LLC)**Submission Date :** JUL 25, 2016**NHTSA Recall No. :** 16V-529**Manufacturer Recall No. :** S55**Manufacturer Information :**

Manufacturer Name : Chrysler (FCA US LLC)

Address : 800 Chrysler Drive  
CIMS 482-00-91 Auburn Hills MI  
48326-2757

Company phone : 1-800-853-1403

**Population :**

Number of potentially involved : 412,855

Estimated percentage with defect : 5 %

**Vehicle Information :**

Vehicle 1 : 2014-2015 Jeep Cherokee

Vehicle Type :

Body Style : SUV

Power Train : NR

Descriptive Information : Certain 2014 and 2015 Jeep Cherokee ("KL") vehicles equipped with either the 9HP48 or 948TE transmission.

Production Dates : NOV 05, 2012 - OCT 31, 2014

VIN Range 1 : Begin : NR End : NR  Not sequential

Vehicle 2 : 2015-2015 Chrysler 200

Vehicle Type :

Body Style : 4-DOOR

Power Train : NR

Descriptive Information : Certain 2015 Chrysler 200 ("UF") vehicles equipped with the 9HP48 or 948TE transmission.

Production Dates : NOV 05, 2012 - OCT 31, 2014

VIN Range 1 : Begin : NR End : NR  Not sequential

Vehicle 3 : 2015-2015 Jeep Renegade

Vehicle Type :

Body Style : SUV

Power Train : NR

Descriptive Information : Certain 2015 Jeep Renegade ("BU") vehicles equipped with the 9HP48 or 948TE transmission.

Production Dates : DEC 09, 2014 - SEP 23, 2015

VIN Range 1 : Begin : NR End : NR  Not sequential

Vehicle 4 : 2015-2015 RAM ProMaster City

Vehicle Type :

Body Style : VAN

Power Train : NR

Descriptive Information : Certain 2015 Ram ProMaster City ("VM") vehicles equipped with the 9HP48 or 948TE transmission.

Production Dates : SEP 10, 2014 - AUG 24, 2015

VIN Range 1 : Begin :

NR

End : NR

Not sequential

## Description of Defect :

Description of the Defect : Some Jeep Cherokee ("KL"), Jeep Renegade ("BU"), Chrysler 200 ("UF"), and Ram ProMaster City ("VM") vehicles may have insufficient crimps in the transmission wire harness that may cause an unexpected shift to neutral resulting in a sudden loss of motive power.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The customer may experience a sudden loss of motive power.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

## Supplier Identification :

### Component Manufacturer

Name : KE Elektronik GmbH

Address : Im Klingefeld 21

Kressberg Marktlustenau FOREIGN STATES 74594

Country : Germany

## Chronology :

Please see the attached supplemental information titled " FCA US LLC Chronology – 9-Speed Harness Crimp – 07122016.pdf".

## Description of Remedy :

Description of Remedy Program : The remedy program for this recall is under development. FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

### Recall Schedule :

Description of Recall Schedule : \*\* 2016 07 25 - Planned Dealer Notification: 8/19/2016. Planned Owner Notification: 8/26/2016

FCA US will provide a dealer notification and owner notification schedule once established.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

\* NR - Not Reported