

Part 573 Safety Recall Report

16V-559

Manufacturer Name : Chrysler (FCA US LLC)**Submission Date :** NOV 04, 2016**NHTSA Recall No. :** 16V-559**Manufacturer Recall No. :** S58**Manufacturer Information :**

Manufacturer Name : Chrysler (FCA US LLC)

Address : 800 Chrysler Drive
CIMS 482-00-91 Auburn Hills MI
48326-2757

Company phone : 1-800-853-1403

Population :

Number of potentially involved : 59

Estimated percentage with defect : 1 %

Vehicle Information :

Vehicle 1 : 2015-2015 RAM 2500

Vehicle Type :

Body Style : PICKUP TRUCK

Power Train : NR

Descriptive Information : Certain 2015 MY Ram 2500 ("DJ") vehicles.

Production Dates : MAY 24, 2014 - JUL 03, 2014

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 2 : 2015-2015 RAM 3500 CAB CHASSIS

Vehicle Type :

Body Style : PICKUP TRUCK

Power Train : NR

Descriptive Information : Certain 2015 MY Ram 3500 Cab Chassis ("DD") vehicles.

Production Dates : MAY 24, 2014 - JUL 03, 2014

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 3 : 2015-2015 RAM 3500

Vehicle Type :

Body Style : PICKUP TRUCK

Power Train : NR

Descriptive Information : Certain 2015 MY Ram 3500 ("D2") vehicles.

Production Dates : MAY 24, 2014 - JUL 03, 2014

VIN Range 1 : Begin : NR End : NR

 Not sequential**Description of Defect :**

Description of the Defect : Certain vehicles may have front track bar frame bracket welds with inadequate fusion which may cause the bracket components to separate from the frame.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : This defect may, in certain cases, result in diminished steering response.

Description of the Cause : NR

Identification of Any Warning that can Occur : Customers may experience an off center steering wheel prior to a failure.

Supplier Identification :

Component Manufacturer

Name : Metalsa

Address : Fracc. Parque Industrial Sta. Mónica
Derramadero-Gral, Cepeda Parras Saltillo FOREIGN STATES 25079

Country : Mexico

Chronology :

Please see the attached supplemental information titled "FCA US LLC Chronology – Track Bar Bracket Frame Welds – 07262016.pdf"

Description of Remedy :

Description of Remedy Program : FCA US will conduct a voluntary safety recall on all affected vehicles to weld on a new track bar frame bracket or reframe the vehicle. FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : ** 2016 09 01 - Dealer Instructions Sept 1 and Owner Letter Sept 8.

FCA US will provide a dealer notification and owner notification schedule once established.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported