

Part 573 Safety Recall Report

16V-699

Manufacturer Name : Newmar Corporation

Submission Date : JAN 30, 2017

NHTSA Recall No. : 16V-699

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street
PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Population :

Number of potentially involved : 71

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2015-2017 Newmar Canyon Star

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain recreational vehicles manufactured by Newmar Corporation, the wheelchair access door with power lock option is not operating as designed. If the remote key fob is pressed while the motorhome is moving the wheelchair access door with power lock will open. This could potentially increase the loss of control of the vehicle resulting in a crash or property damage. Correction: Newmar will add a relay harness so the power door lock will not open with key fob when unit is in transit.

Production Dates : JUN 05, 2014 - JAN 16, 2017

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Description of Defect :

Description of the Defect : On certain recreational vehicles manufactured by Newmar Corporation, the wheelchair access door with power lock option is not operating as designed. If the remote key fob is pressed while the motorhome is moving the wheelchair access door with power lock will open. This could potentially increase the loss of control of the vehicle resulting in a crash or property damage. Correction: Newmar will add a relay harness so the power door lock will not open with key fob when unit is in transit.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the remote key fob is pressed while the motorhome is moving the wheelchair access door with power lock will open. This could potentially increase the loss of control of the vehicle resulting in a crash or property damage.

Amendment: On certain motorhomes the wheelchair access door retains

Description of the Cause : NR

Identification of Any Warning
that can Occur : NR

memory of last command and will complete the action when ignition is turned off. This could result in personal/property damage. Correction: Newmar will add a relay/delay control board with wires to correct this issue.

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

On 9/23/16 Newmar was made aware of the possibility of this defect and on 9/27/16 Newmar gave notice of a recall for units involved.

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs
from Recalled Component : NR

Identify How/When Recall Condition
was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NOV 26, 2016 - NOV 26, 2016

Planned Owner Notification Date : NOV 26, 2016 - NOV 26, 2016

* NR - Not Reported