

Part 573 Safety Recall Report

16V-715

Manufacturer Name : Newmar Corporation**Submission Date :** OCT 05, 2016**NHTSA Recall No. :** 16V-715**Manufacturer Recall No. :** 16V 676**Manufacturer Information :****Population :**

Manufacturer Name : Newmar Corporation

Number of potentially involved : 12

Address : 355 North Delaware Street
PO Box 30 Nappanee IN 46550

Estimated percentage with defect : 100 %

Company phone : 574-773-7791

Vehicle Information :

Vehicle 1 : 2017-2017 Newmar King Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the power steering pump may have an undersized bore in the spool housing. This may cause the spool to stick resulting in reduced power steering fluid flow which may result in an intermittent loss of power steering. This could happen without warning. An intermittent loss of power steering could increase the risk of a crash and/or property damage. Correction: The power steering pump will be replaced.

Production Dates : MAY 12, 2016 - AUG 23, 2016

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 2 : 2017-2017 Newmar Essex

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the power steering pump may have an undersized bore in the spool housing. This may cause the spool to stick resulting in reduced power steering fluid flow which may result in an intermittent loss of power steering. This could happen without warning. An intermittent loss of power steering could increase the risk of a crash and/or property damage. Correction: The power steering pump will be replaced.

Production Dates : MAY 12, 2016 - AUG 23, 2016

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 3 : 2017-2017 Newmar London Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the power steering pump may have an undersized bore in the spool housing. This may cause the spool to stick resulting in reduced power steering fluid flow which may result in an intermittent loss of power steering. This could happen without warning. An intermittent loss of power steering could increase the risk of a crash and/or property damage. Correction: The power steering pump will be replaced.

Production Dates : MAY 12, 2016 - AUG 23, 2016

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 4 : 2017-2017 Newmar Mountain Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the power steering pump may have an undersized bore in the spool housing. This may cause the spool to stick resulting in reduced power steering fluid flow which may result in an intermittent loss of power steering. This could happen without warning. An intermittent loss of power steering could increase the risk of a crash and/or property damage. Correction: The power steering pump will be replaced.

Production Dates : MAY 12, 2016 - AUG 23, 2016

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : On certain motorhomes, the power steering pump may have an undersized bore in the spool housing. This may cause the spool to stick resulting in reduced power steering fluid flow which may result in an intermittent loss of power steering. This could happen without warning. An intermittent loss of power steering could increase the risk of a crash and/or property damage. Correction: The power steering pump will be replaced.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : On certain motorhomes, the power steering pump may have an undersized bore in the spool housing. This may cause the spool to stick resulting in reduced power steering fluid flow which may result in an intermittent loss of power steering. This could happen without warning. An intermittent loss of power steering could increase the risk of a crash and/or property damage. Correction: The power steering pump will be replaced.

Description of the Cause : NR

Identification of Any Warning NR
that can Occur :

Supplier Identification :

Component Manufacturer

Name : NR
Address : NR
NR
Country : NR

Chronology :

Newmar was given notice by Spartan Motors USA on 10/3/16 of a potential defect on Spartan Chassis.

Description of Remedy :

Description of Remedy Program : The power steering pump will be replaced at no charge to the customer.
How Remedy Component Differs NR
from Recalled Component :
Identify How/When Recall Condition NR
was Corrected in Production :

Recall Schedule :

Description of Recall Schedule : NR
Planned Dealer Notification Date : DEC 04, 2016 - DEC 04, 2016
Planned Owner Notification Date : DEC 04, 2016 - DEC 04, 2016

* NR - Not Reported