

Part 573 Safety Recall Report

16V-734

Manufacturer Name : Chrysler (FCA US LLC)**Submission Date :** OCT 18, 2016**NHTSA Recall No. :** 16V-734**Manufacturer Recall No. :** S76**Manufacturer Information :**

Manufacturer Name : Chrysler (FCA US LLC)

Address : 800 Chrysler Drive
CIMS 482-00-91 Auburn Hills MI
48326-2757

Company phone : 1-800-853-1403

Population :

Number of potentially involved : 182,308

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2016-2017 Jeep Wrangler

Vehicle Type :

Body Style : SUV

Power Train : NR

Descriptive Information : All 2016 and 2017 MY Jeep Wrangler ("JK") vehicles built before August 14, 2016.

Production Dates : JUN 16, 2015 - AUG 14, 2016

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : Under certain crash conditions, rotation of the headlamp can cause the sensor wiring to pull and detach from the front impact sensor before a signal is recorded by the Occupant Restraint Controller ("ORC").

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : This defect may result in non-deployment of airbag and pretensioner in certain crash events where deployment is expected, which may increase the risk of injury.

Description of the Cause : NR

Identification of Any Warning
that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR
Address : NR
NR
Country : NR

Chronology :

Please see the attached supplemental information titled "FCA US LLC Chronology - Impact Sensor Wire Routing - 10112016.pdf".

Description of Remedy :

Description of Remedy Program : **2016 10 18 - Rework headlamp harness to move impact sensor branch and change routing to current production design. FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : FCA US will notify dealers and begin notifying owners on or about November 25, 2016.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported