

Part 573 Safety Recall Report

16V-848

Manufacturer Name : Newmar Corporation**Submission Date :** NOV 18, 2016**NHTSA Recall No. :** 16V-848**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Population :

Number of potentially involved : 17

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2017-2017 Newmar King Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the turn signal module has potential to get water inside the cover. If the module becomes wet and the headlights are on, it will cause a back feed to the turn signal. The glass dash display will switch to the turn signal camera mode causing the glass dash to show the turn signal side camera view over the speedometer and RPM displays. This could occur without warning, increasing the risk of a crash and/or property damage. Correction: Dealers will replace the defective module with a new module that is waterproof.

Production Dates : JAN 22, 2016 -OCT 19, 2016

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : On certain motorhomes, the turn signal module has potential to get water inside the cover. If the module becomes wet and the headlights are on, it will cause a back feed to the turn signal. The glass dash display will switch to the turn signal camera mode causing the glass dash to show the turn signal side camera view over the speedometer and RPM displays. This could occur without warning, increasing the risk of a crash and/or property damage. Correction: Dealers will replace the defective module with a new module that is waterproof.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the module becomes wet and the headlights are on, it will cause a back feed to the turn signal. The glass dash display will switch to the turn signal camera mode causing the glass dash to show the turn signal side camera view over

Description of the Cause : NR the speedometer and RPM displays.
Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : NR
Address : NR
NR
Country : NR

Chronology :

On 11/14/16 Newmar was made aware of potential defect. On 11/18/16 Newmar is giving notice of safety defect on 11/18/2016.

Description of Remedy :

Description of Remedy Program : Dealers will replace the defective module with a new module that is waterproof.
How Remedy Component Differs from Recalled Component : NR
Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR
Planned Dealer Notification Date : JAN 17, 2017 - JAN 17, 2017
Planned Owner Notification Date : JAN 17, 2017 - JAN 17, 2017

* NR - Not Reported