

Part 573 Safety Recall Report

16V-942

Manufacturer Name : Jaguar Land Rover North America, LLC**Submission Date :** DEC 22, 2016**NHTSA Recall No. :** 16V-942**Manufacturer Recall No. :** P095**Manufacturer Information :****Population :**

Manufacturer Name : Jaguar Land Rover North America, LLC

Number of potentially involved : 13,500

Address : 555 MACARTHUR BOULEVARD

Estimated percentage with defect : 15 %

MAHWAH NJ 07430

Company phone : 201-760-8534

Vehicle Information :

Vehicle 1 : 2017-2017 Land Rover Discovery Sport

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : NR

Descriptive Information : 2017 MY Land Rover Discovery Sport Vehicles in select VIN range

Production Dates : JUL 14, 2016 - OCT 03, 2016

VIN Range 1 : Begin : SALCP2BGXHH636526 End : SALCR2BG3HH651542 Not sequential

Vehicle 2 : 2016-2017 Land Rover Range Rover

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : NR

Descriptive Information : 2016-2017 MY Land Rover Range Rover Vehicles in select VIN range

Production Dates : JUL 12, 2016 - OCT 26, 2016

VIN Range 1 : Begin : SALGS2EF7GA304537 End : SALGR2PF6GA320320 Not sequentialVIN Range 2 : Begin : SALGS2FV9HA308452 End : SALGS2FK1HA320598 Not sequential

Vehicle 3 : 2016-2017 Land Rover Range Rover Sport

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : NR

Descriptive Information : 2016-2017 MY Land Rover Range Rover Sport Vehicles in select VIN range

Production Dates : JUL 12, 2016 - OCT 26, 2016

VIN Range 1 : Begin : SALWG2KFXGA105581 End : SALWR2PF9GA124030 Not sequentialVIN Range 2 : Begin : SALWG2PF1GA660993 End : SALWG2PF9GA666881 Not sequentialVIN Range 3 : Begin : SALWZ2FE8HA111165 End : SALWR2FE6HA124402 Not sequentialVIN Range 4 : Begin : SALWR2FKXHA663983 End : SALWG2FK8HA666936 Not sequential

Description of Defect :

Description of the Defect : On certain 2016 and 2017 Model Year (MY) Land Rover Range Rover, Land Rover Range Rover Sport and 2017 MY Land Rover Discovery Sport vehicles, the front seatbelt pre-tensioners may not function properly due to a deviation in generant mix ratio.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : In the event of a crash of sufficient severity, the front seatbelt pre-tensioner may fail to operate when required. Failure to operate can lead to increased injuries to the front seat occupants.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NCS Pyrotechnie et Technologies SAS

Address : Rue de la Cartoucherie
BP 90010 Survilliers Fosses FOREIGN STATES

Country : France

Chronology :

See Document "JLR P095 Chronology".

Description of Remedy :

Description of Remedy Program : Owners will be notified and instructed to take their vehicle to an approved Land Rover dealer who will inspect both front seatbelt assemblies for identification of the production date. If the seatbelt production date is from the specified production dates at risk, it will be replaced. If the seatbelt production date is not from the specified production dates at risk, no further action is required. There will be no charge to owners for this repair.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Distribution of owner notification letters will occur on or before February 20, 2017. Notifications to dealers will occur on or before December 28, 2016.

Planned Dealer Notification Date : DEC 28, 2016 - DEC 28, 2016

Planned Owner Notification Date : FEB 20, 2017 - FEB 20, 2017

* NR - Not Reported