



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

## Part 573 Safety Recall Report

# 16V947

**Manufacturer Name:** Chrysler (FCA US, LLC)

**Submission Date:** Jan 29, 2026

**NHTSA Recall No.:** 16V947

**Manufacturer Recall No.:** S92

### Manufacturer Information

### Population

**Manufacturer Name:** Chrysler (FCA US, LLC)

**Address:** 800 Chrysler Drive  
CIMS 482-00-91  
Auburn Hills MI, 48326-  
2757

**Total number of potentially involved:** 12,691

**Estimated percentage with defect:** 1%

### Vehicle Information

**Vehicle 1:** 2009-2009 Chrysler Aspen

**Product Category:**

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Jan 17, 2007 - Dec 18, 2008

**Number of potentially involved:**

**Descriptive Information:**

Certain 2009 MY Chrysler Aspen ("HG") SUVs

**Vehicle 2:** 2010-2010 RAM 3500 Cab Chassis

**Product Category:**

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Sep 25, 2009 - Feb 01, 2010

**Number of potentially involved:**

**Descriptive Information:**

Certain 2010 MY Ram 3500 Cab Chassis ("DC") trucks. Per Alex Ainsley - Actual date range not accepted in portal of 09/25/2009 to 02/19/2010...dates reflected were input to facilitate upload of 573.

### Defect / Noncompliance Description

# Part 573 Safety Recall Report

# 16V947

## Description of the defect or noncompliance:

Some 2010 MY Ram 3500 Cab Chassis (“DC”) and 2009 MY Dodge Durango (“HB”) and Chrysler Aspen (“HG”) vehicles may contain driver airbag (“DAB”) inflators that, after extended exposure to high absolute humidity and heat aging, rupture when deploying during an accident. If the airbag inflator was to rupture, metal fragment(s) may contact the vehicle’s occupant(s), resulting in an increased risk of injury.

**FMVSS1:**

**FMVSS2:**

## Description of the safety risk, including crash, fire, death, injury:

“The Agency has concluded that these non-desiccated frontal Takata [Phase Stabilized Ammonium Nitrate (“PSAN”)] airbag inflators do not pose an unreasonable risk to safety under the Safety Act until they reach a certain level of propellant degradation.” (Takata CO Amendment, ¶18)  
Consequence, as defined by Takata, “in the event of an inflator rupture, metal fragments could pass through the air bag cushion material, which may result in injury or death to vehicle occupants.”

## Description of the cause:

## Identification of any warning that can occur:

## Component Manufacturer

### Tier of Supplier:

### Supplier Type:

**Name:** Takata Corporation

**Address:** 2500 Takata Drive  
Auburn Hills MI, 48326

**Country:** United States

## Involved Components

### Component Name 1:

### Component Description:

### Component Part Number:

# Part 573 Safety Recall Report

**16V947**

## Chronology

Please see attached supplemental information titled "FCA US LLC Chronology- Takata PSAN (Non-Desiccated) DAB Inflators – 2010 MY DC, 2009 MY HB and HG Vehicles"

**Related NHTSA Recall Number:**

## Description of Remedy

**Remedy Type:** Repair

**Consumer Advisories:**  Do Not Drive  Park Outside

**Description of remedy program:**

FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.

**How remedy component differs from recalled component:**

**Identify how/when recall condition was corrected in production:**

## Reimbursement Plan

**Description of reimbursement program:**

**Period of reimbursement:**

**Costs to be reimbursed:**

**Address for reimbursement claims:**

## Recall Schedule

**Description of recall schedule:**

**Part 573 Safety Recall Report****16V947**

\*\* 01/12/17 - Dealer Notification on 01/07/17; Final Owner Letter mailing (start date: 01/11/17, end date: 01/11/17).

FCA US will notify dealers and begin notifying owners on or about February 3, 2017.

**Planned Dealer Notification Date:**

No Dealers

**Planned Interim Owner Notification Date:**

No Owners

**Planned Remedy Owner Notification Date:**

Phased Recall

**Date when VIN will be searchable:**