OMB Control No.: 2127-0004

Part 573 Safety Recall Report

16V-955

Manufacturer Name: Volkswagen Group of America, Inc.

Submission Date: NOV 13, 2017 **NHTSA Recall No.:** 16V-955

Manufacturer Recall No.: VW: 69P4/Audi: 69P2



Manufacturer Information:

Manufacturer Name: Volkswagen Group of America, Inc.

Address: 3800 Hamlin Road

Auburn Hills MI 48326

Company phone: 1-800-893-5298

Population:

Number of potentially involved: 5,947 Estimated percentage with defect: 1 %

Vehicle Information:

Vehicle 1: 2017-2017 Volkswagen Golf R

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: Volkswagen Golf

DRIVER AIRBAG Vehicle count: 5

Production Dates: JUL 27, 2016 - JUL 29, 2016

VIN Range 1: Begin: WVWVF7AU6HW037710 End: WVWWF7AU9HW039911 ✓ Not sequential

Vehicle 2: 2018-2018 Audi Q5

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: Audi Q5

PRETENSIONER Vehicle count: 54

Production Dates: NOV 09, 2016 - JAN 03, 2017

VIN Range 1: Begin: WA1BNAFY6J2000310 End: WA1BNAFY4J2001665 ✓ Not sequential

Vehicle 3: 2017-2017 Audi A6

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: Audi A6

PASSENGER AIRBAG Vehicle count: 135

Production Dates: SEP 05, 2016 - SEP 23, 2016

Vehicle Type:

VIN Range 1 : Begin : WAUG8AFC0HN038449 End : WAUC8AFC4HN043605 ✓ Not sequential Vehicle 4: 2017-2017 Audi A7 Vehicle Type: **Body Style:** Power Train: NR Descriptive Information: Audi A7 PASSENGER AIRBAG Vehicle count: 46 Production Dates: SEP 05, 2016 - SEP 15, 2016 VIN Range 1: Begin: WAUW2AFC5HN038539 End: WAUWFAFC5HN043602 ✓ Not sequential Vehicle 5: 2016-2016 Volkswagen e-Golf Vehicle Type: **Body Style:** Power Train: NR Descriptive Information: Volkswagen e-Golf **DRIVER AIRBAG** Vehicle count: 38 Production Dates: JUL 27, 2016 - AUG 09, 2016 VIN Range 1: Begin: WVWPP7AU5GW914465 End: WVWKP7AU0GW914755 ✓ Not sequential Vehicle 6: 2016-2016 Volkswagen e-Golf Vehicle Type: **Body Style:** Power Train: NR Descriptive Information: Additional e-Golf added 02/17/2017: Driver Airbag Vehicle count: 8 Production Dates: OCT 26, 2016 - NOV 14, 2016 VIN Range 1: Begin: WVWKP7AU0GW916635 End: WVWKP7AU9GW917041 ✓ Not sequential Vehicle 7: 2017-2017 Volkswagen Tiguan Vehicle Type: **Body Style:** Power Train: NR Descriptive Information: Volkswagen Tiguan PASSENGER AIRBAG Vehicle count: 931 Production Dates: SEP 02, 2016 - NOV 16, 2016 VIN Range 1: Begin: WVGAV7AX2HK004766 End: WVGSV7AX6HK009909 ✓ Not sequential Vehicle 8: 2017-2017 Audi Q7

Body Style:

Power Train: NR

Descriptive Information: Audi Q7

PRETENSIONER Vehicle count: 748

Production Dates: JUL 07, 2016 - SEP 28, 2016

VIN Range 1: Begin: WA1VAAF75HD024080 End: WA1LABF71HD031248 ✓ Not sequential

Vehicle 9: 2017-2017 Audi A4 Sedan

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: Audi A4 Sedan

PRETENSIONER
Vehicle count: 2998

Production Dates: JUL 12, 2016 - SEP 21, 2016

VIN Range 1: Begin: WAUANAF47HN027021 End: WAUENAF4XHN038631 ✓ Not sequential

Vehicle 10: 2017-2017 Audi A4 allroad

Vehicle Type : Body Style : Power Train : NR

Descriptive Information: Audi A4 allroad

PRETENSIONER Vehicle count: 348

venicie count. 346

Production Dates: JUL 20, 2016 - SEP 27, 2016

VIN Range 1 : Begin : WA19NAF44HA037545 End : WA19NAF40HA064421 ✓ Not sequential

Vehicle 11: 2017-2017 Volkswagen Golf R

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: Additional Golf R added 02/17/2017: Driver Airbag

Vehicle Count: 38

Production Dates: OCT 19, 2016 - NOV 02, 2016

VIN Range 1: Begin: WVWVF7AU0HW104429 End: WVWWF7AU5HW118539 ✓ Not sequential

Vehicle 12: 2017-2017 Audi A4 Sedan

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: Audi A4 Sedan

HEAD AIRBAG

Vehicle count: 598

Production Dates: SEP 27, 2016 - OCT 18, 2016

VIN Range 1: Begin: WAUGMAF45HA076173 End: WAUENAF49HA077976 ✓ Not sequential

Description of Defect:

Description of the Defect: Affected vehicles have airbag and/or pretensioner igniter(s) manufactured by

Autoliv. The affected igniter(s) may not meet manufacturing specifications. In a crash where airbag and/or pretensioner deployment is needed, an igniter may

not deploy, increasing the risk of injury.

FMVSS 1: NR

FMVSS 2: NR

Description of the Safety Risk: In a crash where airbag and/or pretensioner deployment is needed, an

ignitier may not deploy, increasing the risk of injury.

Description of the Cause: Autoliv has reported that the affected igniters may not actually ignite properly

and fail to ignite the propellant. According to Autoliv this was caused by an improper mixture of the chemicals for the ignition of the first stage inside the

igniter.

Identification of Any Warning NR

that can Occur:

Supplier Identification:

Component Manufacturer

Name: Autoliv B.V. & Co. KG Address: Otto-Hahn-Straße 4

Elmshorn FOREIGN STATES 25337

Country: Germany

Chronology:

On December 06, 2016 Autoliv informed Audi AG and Volkswagen AG of their intent to file a 573 report regarding igniters on December 8, 2016, however without specific information (i.e. serial numbers of affected airbag modules).

On December 20, 2016, Audi AG and Volkswagen AG received datasets for affected components from Autoliv. On December 21, 2016, the matter was presented to Audi AG and Volkswagen AG Product Safety Committees. During the meeting Autoliv advised that serial number lists provided may not be accurate and are subject to review. Updated lists are expected to be provided by Autoliv to Audi AG and Volkswagen AG on January 06, 2017. However, based on the facts presented to the Audi AG and Volkswagen AG Product Safety Committees, a determination of defect was made.

Date of Determination: December 21, 2016

On February 17, 2017 Autoliv informed Volkswagen AG of additional vehicles impacted by this recall. Based upon this information, the Volkswagen AG Product Safety Committee made a defect determination and will recall these additional vehicles. Date of determination for additional vehicles: February 17, 2017.

Description of Remedy:

Description of Remedy Program: Affected airbags/pretensioners will be replaced with properly

manufactured parts.

How Remedy Component Differs Autoliv reported to have corrected the issue with the igniter chemicals in

from Recalled Component: their production.

Identify How/When Recall Condition Autoliv reported to have corrected the issue by September 21, 2016 in was Corrected in Production: their production; however this does not reflect the Audi AG or Volkswagen

AG vehicle production dates. Affected vehicles will be identified by module

serial numbers after Autoliv has provided them to Audi AG and

Volkswagen AG.

Recall Schedule:

Description of Recall Schedule: Dealer and customer notifications are TBD

Planned Dealer Notification Date: FEB 09, 2017 - FEB 09, 2017 Planned Owner Notification Date: FEB 28, 2017 - MAR 01, 2017

* NR - Not Reported