

[Next Unread Message](#)**View Message**

Sent on	02	17	2017	Expires on	05	17	2017
----------------	----	----	------	-------------------	----	----	------

From	Brad Ortloff, Manager of Campaign Administration
-------------	--

Subject	UPDATE: 2015-16 ILX & RDX Driver's Airbag Inflator Safety Recall
----------------	--

DATE: February 17, 2017

TO: All Acura Parts & Service Managers, Advisors and Personnel

FROM: Brad Ortloff, Manager of Campaign Administration

RE: UPDATE: 2015-16 ILX & RDX Driver's Airbag Inflator Safety Recall

On January 29, 2016, Acura launched a safety recall for certain 2005-16 Acura vehicles due to airbag inflators that may deploy abnormally after prolonged exposure to high temperature and high absolute humidity. These vehicles require removal of the driver's airbag inflator and replacement with a new, non-Takata inflator per the instructions outlined in service bulletin 16-010, *Safety Recall: Takata Driver's Airbag Inflator*.

Note: Some vehicles affected by this campaign may be in your vehicle inventory. Failure to repair a vehicle subject to a recall or campaign may subject your dealership to claims or lawsuits from the client or anyone else harmed as a result of such failure.

For administrative purposes, the 2015-16 ILX & RDX models are being removed from service bulletin 16-010, and a new service bulletin, 17-004, *Safety Recall: 2015–16 ILX and RDX Takata Driver's Airbag Inflator* has been posted. Please disregard previous versions of 16-010 that include the 2015 & 2016 model applications. Instead, the revised version of 16-010 should apply to 2005-14 vehicles, and 2015 & 2016 ILX & RDX should use the information available in the newly posted 17-004. Claims for repair orders opened on or before February 16, 2017 should use the Warranty information listed in service bulletin 16-010, and claims made afterwards should use the information available in 17-004. Please note that claims filed for 2015 & 2016 vehicles using the incorrect Warranty information will result in rejection.

No change has been made to any parts or repair information listed; only the Warranty claim information has been revised in the new bulletins.

Click [here](#) for a revised copy of 16-010.

Click [here](#) for a copy of 17-004.