

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS4931
URGENT - DISTRIBUTE IMMEDIATELY

Date: December 13, 2018

Subject: GM Dealers Servicing Saab Vehicles with Open Safety Recalls

GM Bulletin 15027-01
Driver's Seat Belt Replacement
2004-2011 Saab 9-3 Convertible
(Also Requiring Completion of 15041-05 or 15043-05)

GM Bulletin 15041-05
Driver's Air Bag Replacement
2006-2011 Saab 9-3 and 2006-2009 Saab 9-5
(Never Registered in High Absolute Humidity Areas)

GM Bulletin 15043-05
Driver's Air Bag Replacement
2006-2011 Saab 9-3 and 2006-2009 Saab 9-5
(Currently or Previously Registered in High Absolute Humidity Areas)

To: All General Motors Dealers

The subject recall bulletins were originally intended for Cadillac dealers only, but have been revised to clarify that all GM dealers are now authorized to perform the required repairs. Please see the attached bulletins for details and discard all previous copies of bulletins 15027, 15041-04 and 15043-04.

Dealers who have any of the involved vehicles in their used vehicle inventory, are strongly encouraged to perform the required repairs as quickly as possible and certainly prior to vehicle sale.

For bulletins 15041-05 and 15043-05, the attached procedure is being provided to allow dealers to load Saab software to their Tech 2 – 32 bit memory card. Providing technicians with Saab diagnostic information will allow them to properly complete all service procedure steps. Note that upon completion of the required service procedure, the Saab software can be removed and the card reloaded with the GM North American software.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS