



SUBJECT

Recall Campaign 16V-XXX: Driver-Side Front Air Bag Module

MODEL

E70 (X5 incl M)

E71 (X6 incl M)

E72 (X6 ActiveHybrid)

E90 (3 Series Sedan incl M)

E91 (3 Series Sportswagon)

E92 (3 Series Coupe incl M)

E93 (3 Series Convertible, incl M)

E82 (1 Series coupe)

E83 (X3)

E84 (X1)

E88 (1 Series convertible)

SITUATION

BMW AG is conducting a Voluntary Safety Recall involving Driver-Side Front Air Bag Module on certain BMW vehicles that are equipped with non-desiccated Takata PSDI-5 inflators. These vehicles, covering model years 2006-2015 have not been part of earlier Takata-related air bag recalls.

There are approximately 840,000 vehicles in the US.

Model	Model Year	Approx .Volume	Production Dates
1 Series Coupe (incl. M)	2008 – 2013	32,620	Nov 2007 – Oct 2013
1 Series Convertible	2008 – 2013	28,160	Nov 2007 – Oct 2013
3 Series Sedan (incl. M)	2006 – 2011	132,845	Feb 2005 – Dec 2011
3 Series Sedan (diesel)	2009 – 2011	4,160	Mar 2008 – Aug 2011

3 Series Sports Wagon	2006 – 2012	3,270	Jun 2005 – May 2012
3 Series Coupe (incl. M)	2007 – 2013	129,515	Apr 2006 – Jun 2013
3 Series Convertible (incl. M)	2007 – 2013	99,810	Nov 2006 – Oct 2013
X1 SAV	2013 – 2015	57,290	Feb 2012 – Sep 2014
X3 SAV	2007 – 2010	64,925	Aug 2006 – Aug 2010
X5 SAV (incl. M)	2007 – 2013	214,580	Sep 2006 – Jun 2013
X5 SAV (diesel)	2009 – 2013	35,440	Mar 2008 – Jun 2013
X6 SAV (incl. M)	2008 – 2014	37,000	Jul 2007 – Jun 2014
X6 SAV ActiveHybrid	2010 – 2011	365	Mar 2009 – Sep 2011

At this time, a repair solution is being developed, we will provide an update as more information becomes available.

For your reference, Q&A and recall notice has been attached.

ATTACHMENTS

View PDF attachment [B650416 Q&A](#).

View PDF attachment [B650416 Recall Notice](#).

[Copyright ©2016 BMW of North America, Inc.]