

GLOBAL SAFETY FIELD INVESTIGATIONS  
DCS3988  
URGENT - DISTRIBUTE IMMEDIATELY

Date: April 6, 2016

Subject: 31820C - Noncompliance Recall  
Side Impact Airbag Weld Stud Fractures  
Revised Service Procedure

Models: 2016 Chevrolet Malibu

To: All Chevrolet Dealers

This bulletin is being revised with an update to the VIN list with seat airbag module locations. The new list includes dealer BAC's and stock/sold information. The service procedure has also been updated with additional instructions on the search function for the VIN list. Please discard all copies of 31820B.

END OF MESSAGE  
GLOBAL SAFETY FIELD INVESTIGATIONS