

SERVICE BULLETIN 541: FUEL TANK SUBHARNNESS



Notice Information

Ref: 857
 Posted Date: 11/2/2016 10:14:45 AM
 Posted To: Dealer Principal, Service / Technical, Motorcycle Sales, Franchise/Brand Manager, Sales Manager, Workshop Manager, Service Reception, Dealer Admin
 Subject: Service/Technical

TOL NOTICE (US&CAN) – November 2, 2016

Service Bulletin 541: Fuel Tank Subharness

Triumph has just released Service Bulletin 541. Internal investigations have identified the need to replace a subharness in the fuel tank to prevent a potential fuel leak.

Affected Motorcycles

New Bonneville family models listed in the VIN ranges below:

Fuel Tank Subharness			
Bulletin Number	Models Affected	VIN Range	
541	Bonneville T100	759204	794799
	Bonneville T100 Black	765369	794585
	Thruxton 1200	743684	793611
	Thruxton 1200R	740405	794605
	Street Twin	731919	794789
	Bonneville T120	739727	794802
	Bonneville T120 Black	741136	794575
	Street Cup	780697	794796

Note:

- Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory.
- The modified motorcycles can be identified by checking the 'Outstanding Service Bulletins' on Warranty Online.

IMPORTANT NOTICE

STOP DELIVERY OF AFFECTED MOTORCYCLES IMMEDIATELY.

DO NOT deliver a motorcycle affected by this Safety Recall Action Notice to a customer until you have completed, or confirmed completion of, the procedures described in this Safety Recall Action Notice.

Delivering a motorcycle subject to an outstanding Safety Recall Action Notice may contravene local or national laws in your market, territory or country.

Please consult this attached **Service Bulletin 541 PDF** and see **Service Bulletin Page** in TOL for complete instructions. If you have any questions, contact Triumph 24/7 Customer Support at (888) 284-6288.

Triumph Motorcycles (America) Ltd, 100 Hartsfield Centre Parkway, Suite 200, Atlanta Georgia, 30354, UNITED STATES
Tel: 001 6788 542010, Fax: 001 6788 542025

