



SI B65 11 16
Audio, Navigation, Monitors, Alarms, SRS

March 2016
Technical Service

This Service Information bulletin supersedes SI B65 11 16 **dated March 2016.**

SUBJECT

NEW Delivery Stop – Electronic Control Unit for Air Bags

MODEL

G12 (7 Series)

NEW SITUATION

A Delivery Stop was issued on vehicles produced from July 1, 2015 to December 11, 2015. This is now a Voluntary Safety Recall involving the replacement of the Electronic Control Unit for the Air Bags (ACSM5) on certain G12 (7 Series) BMW vehicles. In these vehicles an electronic control unit for the air bags might malfunction in very rare instances. In such instances, an “air bag warning” light will illuminate in the instrument cluster.

Affected vehicles in dealer inventory must not be retailed or delivered until this issue is corrected. Vehicles at ports of entry will be repaired prior to dealer delivery.

Affected vehicles can be identified with a “Vehicle Comment” in DCS Warranty Vehicle Inquiry or ISPA light with the description:

- This vehicle is identified in Recall 16V-XXX Replace Electronic Control unit for the Air Bags. No action at this time, repair is being developed. Do not sell vehicle until Recall is performed. See Service Information Bulletin B65 11 16

This bulletin will be updated with repair instructions and warranty information when it becomes available.

ATTACHMENTS

View PDF attachment [B651116 Delivery Stop Legal](#).

View PDF attachment [16V-xxx-MY16-G12-AirBagControlModule\(QA\)](#).

[Copyright ©2016 BMW of North America, Inc.]