



**NOTIFICATION OF SAFETY RECALL J059:  
REPLACEMENT OF THE FUEL OUTLET  
MOUNTING FLANGE**

**SERVICE BULLETIN**

05-APR-16 | No.: 7-105USA | SEC.: RECALL | MKT.: USA

*Jaguar Land Rover North America, LLC has informed the National Highway Traffic Safety Administration (NHTSA) of its intent to perform a Non-Compliance Recall on certain 2010 model year Jaguar XF vehicles imported into the United States market. Information relating to the Recall will be posted on the National Highway Traffic Safety Administration website.*

*United States Federal regulations require that retailers must be advised of this Recall notification within three working days after government notification.*

*United States Federal law requires retailers to complete any outstanding safety Recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a retailer could result in a civil penalty of up to \$21,000.00 per vehicle.*

*This Recall Service Bulletin serves as notification to all Jaguar retailers in the United States and Puerto Rico that any affected new vehicles may not be sold and delivered for customer use until the Recall repair is completed.*

**DESCRIPTION**

A potential issue has been identified on a limited number of vehicles listed in the *Affected Vehicle Range* where a fuel odor is present, the amber Malfunction Indicator Lamp on the Instrument Cluster is illuminated, and/or liquid fuel is on the ground.

**AFFECTED VEHICLE RANGE**

A total of 28 2010 model year XF (X250) vehicles are potentially involved in the USA and Puerto Rico.

**XF (X250)**

**Model Year:** ..... 2010

**VIN:** ..... SAJWA0HB1ALR43674-SAJWA0GB3ALR46304

**EFFECT ON VEHICLE OPERATION**

The driver may also experience fuel odor and in some circumstances, with the vehicle static, there could be liquid fuel underneath the rear of the vehicle, which in the presence of an ignition source could lead to a fire.

**SERVICE PROGRAM / REWORK ACTION**

Owners will be notified by mail and instructed to take their vehicle to a Jaguar retailer who will replace the fuel outlet mounting flange with a component of revised design.

There will be no charge to owners for this action.

**OWNER NOTIFICATION**

Owner notification is expected to occur on or before 20 May 2016.

**ACTION TO BE TAKEN**

Check DDW to ensure that the vehicle is affected by this program (**J059**) prior to undertaking any rework action.

Retailers are required to **HOLD** only affected new vehicles that are within your control and refrain from releasing the vehicles for **new vehicle sale** pending completion of the rework action.

Sold vehicles will be subject to the standard Recall notification and Recall bulletin process detailing the action required for vehicles in the hands of owners.

A Technical Bulletin will be published once repair instructions are finalised and all required parts have been procured.

**Retailers are advised that the use of affected vehicles as Sales Demonstrator or Service Loaner vehicles may be considered a violation of Federal legislation. Jaguar Land Rover North America, LLC recommends against using affected vehicles for demonstrator or loaner purposes. Please consult your own legal counsel if you have questions in this regard.**

Thank you for your cooperation in this matter. Jaguar Land Rover North America apologizes for any inconvenience this may cause.

