

GLOBAL SAFETY FIELD INVESTIGATIONS  
DCS4308  
URGENT - DISTRIBUTE IMMEDIATELY

Date: January 11, 2017

Subject: 15822C – Safety Recall  
Seatbelt Lap Anchor Tensioner Cable – Driver's Side  
Revised Correction, Part Information, Service Procedure, Warranty  
Transaction Information sections

Models: 2014-2015 Chevrolet Silverado 1500 Series  
2014-2015 GMC Sierra 1500 Series

To: All General Motors Dealers

This bulletin has been revised to provide an amended service procedure. Specifically, dealers will no longer be required to remove, modify and reinstall the seat side shield. Effective immediately, dealers are to remove and replace the seat side shield. The Correction, Part Information, Service Procedure, and Warranty Transaction Information sections have been revised accordingly. All vehicles previously repaired with a modified seat side shield do not require any additional repairs and the recall is considered closed. Please discard all copies of bulletin 15822B.

END OF MESSAGE  
GLOBAL SAFETY FIELD INVESTIGATIONS