

GLOBAL SAFETY FIELD INVESTIGATIONS  
DCS4105  
URGENT - DISTRIBUTE IMMEDIATELY

Date: July 7, 2016

Subject: 15822B – Safety Recall  
Seatbelt Lap Anchor Tensioner Cable – Driver's Side  
Revised Service Procedure, Part Information, and Warranty  
Transaction Information sections, Customer Letter Added

Models: 2014-2015 Chevrolet Silverado 1500 Series  
2014-2015 GMC Sierra 1500 Series

To: All Chevrolet and GMC Dealers

A final remedy is now available for new, unused, and unsold vehicles in dealer inventory with 50 miles (80 km) or more on the odometer and GM Certified used vehicles in dealer's possession. Vehicles in used inventory and customer vehicles that were inspected, and if necessary, repaired under the interim inspection procedure will also require additional repair as the final remedy. The part information, service procedure, and warranty transaction information sections have been revised. Additionally, a copy of the customer notification letter has been included. Please discard all copies of bulletin 15822A.

**Customer Letter Mailing**

The customer letter mailing will begin on July 11, 2016.

END OF MESSAGE  
GLOBAL SAFETY FIELD INVESTIGATIONS